

ministerie van verkeer en waterstaat  
*Ministry of Transport and Public Works*

**rijksluchtvaartdienst**  
*Department of Civil Aviation*

BLA nr: 91-038

Date : May 10, 1991



**directie luchtvaartinspectie**  
*Aeronautical Inspection Directorate*

F O K K E R

C O R R E C T I O N

Type: F.27

Seq.: 100

Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)**

**NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.*

**LANDING GEAR - BRAKE CONTROL VALVE ACTUATING LEVERS - REPLACEMENT**

**Description:**

Reports have been received of brake control valve actuating levers that fractured during operation of the brake system. Subsequent investigation showed that the levers initially cracked due to fatigue and finally fractured due to overload. To prevent recurrence, this Airworthiness Directive (BLA) requires the replacement of the brake control valve actuating levers with improved units, manufactured from stainless steel with high tensile strength.

**Effectivity:**

F.27 aircraft (except Mk.050), all serial numbers

**Effective date:**

May 17, 1991

**Compliance:**

required before accumulating 2,000 flight hours after the effective date of this AD, or before May 01, 1992, whichever comes first.

**Accomplishment:**

in accordance with Fokker Service Bulletin F27/32-161 dated June 05, 1989 or a later RLD-approved revision.

**Remarks:**

- In respect to Art.88 par.3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

**Note:** Address inquiries regarding this AD to:

Department of Civil Aviation  
Aeronautical Inspection Directorate  
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands  
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63163 or -63120  
Telefax: ()-31-(0)2503-40741