

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

BLA nr: 91-070

Date : July 19, 1991



directie luchtvaartinspectie
Aeronautical Inspection Directorate

F O K K E R

Type: F.28 Mk.0100

Seq.: 082

Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

FUSELAGE - NOSE RADOME LATCH BRACKET ATTACH BOLTS - REPLACEMENT

Description:

On some aircraft, the blind bolts which attach the latch brackets to the nose radome appear to have been installed incorrectly. As a result, the bolts and brackets can become disengaged, raising the possibility of losing the nose radome. To prevent such incidents, this Airworthiness Directive requires the affected bolts to be replaced, using the correct installation procedure.

Effectivity:

F.28 Mk.0100 aircraft serial numbers:

11290, 11296, 11298, 11299, 11301, 11306, 11308, 11310 and 11313

Effective date: July 26, 1991

Compliance: required before July 01, 1992

Accomplishment: in accordance with Fokker Service Bulletin F100-53-067 dated July 01, 1991 or a later RLD-approved revision.

Remarks:

- In respect to Art.88 par.3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

Note: Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63168 or -63122
Telefax: ()-31-(0)2503-40741

ISSN 0920 - 1084