

**M.A.L.**

(MEDEDELINGEN  
AAN NEDERLANDSE  
LUCHTVARENDEN  
EN EIGENAREN VAN  
LUCHTVAARTUIGEN)

**NEDERLAND**

RIJKSLUCHTVAARTDIENST  
LUCHTVAARTINLICHTINGDIENST

23/70

4 mar

(AIR 367)

KANAALWEG 3 - SCHEVENINGEN - TELEFOON 070-51 23 81 (T. 369)

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZINGEN  
(BLA)**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.*

**70-18-26**

**Fokker F.28**

**Betreft** : -Fire Protection- Engine fire extinguishing system-  
**Subject** correction of wire length and introduction of placards  
near bottles.

**Van toepassing op** : F.28 Aircraft serial numbers 11004  
**Applies to** to 11016 inclusive.

**Tijdstip van uitvoering** : Required before June 1, 1970.  
**Compliance**

**Datum van inwerkingtreding** : March 4, 1970.  
**Effective date**

**Uitvoering** : In accordance with Fokker Service  
**Accomplishment** Bulletin F.28/26-2 dated 5 February,  
1970.

*All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*

Note: Address inquiries regarding this Airworthiness Directive to:

Aeronautical Inspection Division  
Department of Civil Aviation  
P.O. Box 7555  
Schiphol - East  
Netherlands.