


<b>EASA</b>	<b>AIRWORTHINESS DIRECTIVE</b>	
	<b>AD No : 2005-0013</b>	
	<b>Issued/Date: 1 April 2005</b>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
Type Approval Holder's Name AB "Sportinė aviacija"	Type/Model designation(s) LAK-19	
TCDS Number: EASA.A.012		
Foreign AD No.: N/A		
Supersedure: N/A		

ATA 02 - FLIGHT MANUAL AND MAINTENANCE MANUAL –Replacement of individual pages

Manufacturer:	AB "Sportinė aviacija"; Pociūnai, LT-59327, Lithuania
Applicability:	Different actions for different serial numbers: LAK-19 s/n 001 not affected; s/n 002 and 003 affected except paragraph 5.2.2 and paragraph 5.2.4 of the SB No. 019.4.00.002; s/n 004 and all further s/n affected except paragraph 5.2.1 of the SB. (for your information: The highest S/N affected is still open)
Reason:	Consideration of the latest design changes of the sailplane LAK-19 in the Flight and Maintenance Manuals, e.g. extra layer in the wing, removal of the production weight from the manuals, etc.. Additional corrections on various paragraphs of the manuals. The pages of the manuals to be replaced are defined in the Service Bulletin No. 019.4.00.002. Exchange of the Cockpit Data Placard.
Approval No. and date	EASA approval reference No 2005-383 dated 10 January 2005
Effective Date:	31 May 2005
Compliance:	Before 31 May replacement of the affected pages of the sailplane <b>LAK-19</b> Flight Manual and Maintenance Manual. Exchange of the Cockpit Data Placard in accordance with AB "Sportinė aviacija" Service Bulletin No. 019.4.00.002.

Ref. Publications:	AB "Sportinė Aviacija" Service Bulletin No. 019.4.00.002 which is available from the manufacture: "AB Sportinė aviacija", Pociūnai, LT-59327, Lithuania
Remarks:	<p>This AD was posted for consultation as PAD 05-004 on 18 February 2005. Comments were requested before 11 March 2005. None were received.</p> <p>Enquiries regarding this Airworthiness Directive should be referred to Mr. Roger Hardy, EASA Certification Manager General Aviation; <a href="mailto:roger.hardy@easa.eu.int">roger.hardy@easa.eu.int</a>.</p> <p>EASA Postfach 10 1253 D-50 452 Köln Germany</p> <p>For questions concerning the technical contents of this AD's requirements contact AB "Sportinė aviacija", the address is listed above.</p>