

 Direction générale de l'aviation civile France GSAC publication	AIRWORTHINESS DIRECTIVE No F-2005-012 R1		Distribution: B	Issue date: February 16, 2005	Page : 1/1
	This Airworthiness Directive is published by the DGAC on behalf of EASA, Airworthiness Authority of the State of Design for the affected product, part or appliance.			<i>Translation of « Consigne de Navigabilité » of same number. In case of difficulty, reference should be made to the French issue.</i>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry.					
Corresponding foreign Airworthiness Directive(s): Not applicable			Airworthiness Directive(s) replaced: F-2005-012 original issue		
Person in charge of airworthiness: DASSAULT AVIATION			Type(s): FALCON 900EX and FALCON 2000EX aircraft		
Type certificate(s) No. 163, A.008 TCDS No 163, A.008					
ATA chapter: 31		Subject: Indicating Recording Systems - NIC (Honeywell EPIC Network Interface Controllers) timing issue			

CANCELLATION NOTICE

This Revision 1 cancels Airworthiness Directive (AD) F-2005-012, which is replaced by AD F-2005-024 for FALCON 900EX and by AD F-2005-025 for FALCON 2000EX.

This AD Revision is approved under EASA reference No 2005-1381 dated February 09, 2005.

EFFECTIVE DATES :

Original issue	:	Upon receipt of the Emergency AD issued on January 13, 2005
Revision 1	:	January 27, 2005.