EASA	AIRWORTHINESS DIRECTIVE CANCELLATION NOTICE	
*	AD No.: 2011-0188-CN	
	Date: 27 September 2011	
6	accordance with Regulation (tive (AD) Cancellation Notice (CN) is issued by EASA, acting in EC) No 216/2008 on behalf of the European Community, its ropean third countries that participate in the activities of EASA tion.
Type Approval H	lolder's Name :	Type/Model designation(s) :
AIRBUS		A319 and A320 aeroplanes
TCDS Number:	EASA.A.064	
Foreign AD:	Not applicable	
Cancellation:	This Notice cancels DGAC France AD F-2001-499 R4 dated 31 August 2005, EASA approval 2005-6191.	
ATA 32	GOODRICH carbon brake - Reduction of performances	
Manufacturer(s):	Airbus (formerly Airbus Industrie)	
Applicability:	Airbus A319 and A320 aeroplanes, all certified models and serial numbers which are equipped with Goodrich carbon brakes, Part Number (P/N) 2-1526-4, or P/N 2-1526-5, or P/N 2-1572, or P/N 2-1598-1, or P/N 2-1600-1 or P/N 2-1600-2 or P/N 2-1600-3, which has been installed in accordance with:	
	 Airbus modification 24007 or 24260 or 25810 or 30075 or 31146 or 31803 in production, or 	
	 Airbus Service Bulletin (SB) A320-32-1090 or A320-32-1114 or A320-32-1180 or A320-32-1221 (modification 30485) or A320-32-1228 or A320-32-1238 in service. 	
Reason:	According to information provided by Airbus to EASA, Airbus SB A320-32-1247 (modification 32311), which constitutes a terminating action for the requirements of DGAC France AD F-2001-499 R4, has been declared embodied on all affected aeroplanes by operators. As such, the Airplane Flight Manual (AFM) Temporary Revision required by DGAC France AD F-2001-499 R4 is no longer provided to operators for inclusion in the AFM. In addition, the affected P/N carbon brakes are no longer available as replacement parts. Consequently, the unsafe condition that was addressed by DGAC France AD F-2001-499 R4 no longer exists and cannot develop on any aeroplane.	
	For the reasons described above, this Notice cancels DGAC France AD F-2001-499 R4.	
Effective Date:	27 September 2011	

EASA Form 116 Page 1/2

Required Action(s) and Compliance Time(s):	Not applicable	
Ref. Publications:	Airbus SB A320-32-1247 Revision 02 dated 06 January 2005.	
Remarks :	This CN was posted on 10 August 2011 as PAD 11-085-CN for consultation until 07 September 2011. No comments were received during the consultation period.	
	 Enquiries regarding this CN should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail ADs@easa.europa.eu. 	
	 For any question concerning the technical content of this CN, please contact: AIRBUS – Airworthiness Office – EIAS, Fax +33 5 61 93 44 51; E-mail: account.airworth-eas@airbus.com. 	

EASA Form 116 Page 2/2