

EASA	AIRWORTHINESS DIRECTIVE
	<p>AD No.: 2013-0269</p> <p>Date: 07 November 2013</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].	
Design Approval Holder's Name: AIRBUS	Type/Model designation(s): A340 aeroplanes
TCDS Number:	EASA.A.015
Foreign AD:	Not applicable
Supersedure:	This AD supersedes EASA AD 2008-0026 dated 12 February 2008, EASA AD 2008-0160 dated 22 August 2008 and EASA AD 2012-0021 dated 30 January 2012.
ATA 05	Time Limits and Maintenance Checks – Ageing Systems Maintenance – ALS Part 4 – Amendment
Manufacturer(s):	Airbus (formerly Airbus Industrie)
Applicability:	Airbus A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, A340-542, A340-642 and A340-643 aeroplanes, all manufacturer serial numbers.
Reason:	<p>The airworthiness limitations for Airbus aeroplanes are currently published in Airworthiness Limitations Section (ALS) documents.</p> <p>The airworthiness limitations applicable to the Ageing Systems Maintenance (ASM) are given in Airbus A340 ALS Part 4, which is approved by EASA.</p> <p>Revision 03 of Airbus A340 ALS Part 4 introduces more restrictive maintenance requirements and/or airworthiness limitations. Failure to comply with these instructions could result in an unsafe condition.</p> <p>For the reason described above, this AD retains the requirements of EASA AD 2012-0021, which is superseded, and requires accomplishment of the actions specified in Airbus A340 ALS Part 4 at Revision 03.</p> <p>In addition, this AD also supersedes EASA AD 2008-0026 and EASA AD 2008-0160, whose requirements applicable to A340 aeroplanes have been transferred into Airbus A340 ALS Part 4.</p>

Effective Date:	21 November 2013
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <ol style="list-style-type: none"> (1) From the effective date of this AD, within the compliance times defined in the Record of Revisions (ROR) pages of Airbus A340 ALS Part 4 Revision 03, accomplish the following actions, depending on aeroplane configuration, as specified in Airbus A340 ALS Part 4 Revision 03: <ol style="list-style-type: none"> (1.1) Replace each component before or upon reaching the applicable life limit, and (1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks. (2) If, during accomplishment of any task as required by paragraph (1) of this AD, discrepancies are detected, within the applicable compliance time specified in the Airbus maintenance documentation, accomplish the applicable corrective actions in accordance with the instructions specified (or incorporated by reference) in the applicable Airbus maintenance documentation. <p>If no compliance time is identified in the Airbus maintenance documentation, before next flight, accomplish the corrective actions, or contact Airbus for approved instructions and, within the compliance time specified therein, accomplish those instructions accordingly.</p> <p>If any of the discrepancies detected during accomplishment of any task as required by paragraph (1) of this AD is not defined in the Airbus maintenance documentation, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.</p> (3) Compliance with the requirements of paragraphs (1) and (2) of this AD can be demonstrated by: <ol style="list-style-type: none"> (3.1) Revising as follows the approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane: <p>Incorporate all maintenance requirements and associated airworthiness limitations, as specified in Airbus A340 ALS Part 4 Revision 03, as applicable to aeroplane type, and incorporate the compliance information as specified in paragraph (2) of this AD, and</p> (3.2) Complying with the approved AMP described in paragraph (3.1) of this AD.
Ref. Publications:	<p>Airbus A340 ALS Part 4 Revision 03, approved by EASA on 15 November 2012.</p> <p>The use of later approved variations or revisions of this document is acceptable for compliance with the requirements of this AD.</p>
Remarks:	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. This AD was posted on 03 October 2013 as PAD 13-153 for consultation until 24 October 2013. No comments were received during the consultation period. 3. Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu. 4. For any question concerning the technical content of the requirements in this AD, please contact: Airbus – Airworthiness Office – EIAL; E-mail: airworthiness.A330-A340@airbus.com.