



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0172-E	Initial Issue	15/06/2007	EADS Socata	TBM 700	Doors – Passenger door locking handle – Inspection / Modification
2007-0170	Initial Issue	15/06/2007	Saab Aircraft AB	SAAB SF340A and SF340B	Fuel Tank Safety - Fuel - Indicating – Wire separation of Fuel Quantity Indication System (FQIS) Wiring - Wing
2007-0169	Initial Issue	15/06/2007	Saab Aircraft AB	SAAB SF340A and SF340B	Fuel Tank Safety Fuel - Indicating – Wire separation of Fuel Quantity Indication System (FQIS) Signal Conditioner 28 VDC supply - Fuselage
2007-0168	Initial Issue	15/06/2007	Saab Aircraft AB	SAAB SF340A and SAAB 340B	Fuel Tank Safety Wing – Fuel Access Door – Improved Sealing
2007-0167	Initial Issue	15/06/2007	Saab Aircraft AB	SAAB 2000	Fuel Tank Safety - Wings – Fuel Access Door – Improved Sealing
2007-0166	Initial Issue	15/06/2007	Airbus	A330 aircraft	Exhaust – Thrust Reverser Hinge n°5 – Sleeve and Pin Replacement
2007-0165	Initial Issue	14/06/2007	Eurocopter Deutschland GmbH	EC135 and EC635 helicopters	Electrical Power – DC Power Supply Lines – Modification
2007-0164	Supersedure	14/06/2007	ATR - Avions de Transport Régional	ATR 42 and ATR 72 aircraft	Equipment & Furnishings - Thermal/Acoustical Insulation Blankets - Replacement/Removal
2007-0156	Correction	14/06/2007	Honeywell International	RCZ-833J/K, -851J/K, and -854J Communication Units, equipped with XS-852E/F Mode S Transponders; and XS-856A/B and -857A Mode S Transponders	Communication – Comm Units & Transponders – Modification / Replacement
2007-0105	Correction	14/06/2007	Eurocopter	AS 332 and SA 330 series helicopters	Equipments / Furnishings - Safeying of Hoist Plate Front Attachment – Check / Modification / Test
2007-0078	Initial Issue	14/06/2007	Apex Aircraft	DR 400/500	Carbon monoxide contamination - cabin air outlet and main fuel tank aft wall - Inspection / Modification
2007-0163	Supersedure	11/06/2007	Airbus	A318, A319, A320 and A321 series	Flight Controls – Elevator Backlash – Inspection
2007-0162	Supersedure	11/06/2007	Airbus	A321	Wings – Rear Spar - Inspection
2007-0161	Initial Issue	11/06/2007	Airbus	A318, A319, A320 and A321 aircraft	Fuselage – Centre Fuselage – Main Landing Gear Door Keel Beam Hinge and Actuator Fitting - Inspection
2007-0065R1	Revision	11/06/2007	Airbus	A318, A319, A320 and A321 series	Landing gear – Normal extension and retraction – Inspection of the selector valves 40GA and 41GA
2006-0153R2	Revision	11/06/2007	Airbus	A318, A319, A320 and A321 aircraft	Auxiliary Power Unit (APU) - Starter Motor and Air Intake System – Inspection/Cleaning
2007-0160-E	Initial Issue	07/06/2007	Agusta S.p.A	A109E; A109LUH; A109S; A119	Equipment & Furnishings - Cargo Hook P/N 528-010-01 / Lever P/N 232-028-00 - Inspection
2007-0159-E	Initial Issue	06/06/2007	Eurocopter	EC 155	Equipment / Furnishings - Hoist cut-off connector 24 Delta - Inspection / Modification
2007-0067R1	Revision	06/06/2007	Airbus	A319, A320	Wing - Center and Outer Wing Box at level of Rib 1 Junction - Inspection
2007-0158	Supersedure	04/06/2007	Airbus	A340 Aircraft	Time Limits - Damage Tolerant Airworthiness Limitations Items (ALI)



<i>AD Number</i>	<i>Status</i>	<i>Approval's Date</i>	<i>TC-Holder</i>	<i>Type/Model</i>	<i>Subject</i>
2007-0157	Supersedure	04/06/2007	Airbus	A310, A300-600	Fuselage – Aft Pressure Bulkhead Attachment Angles – Modification and Inspection Program