



Publ. number	Issue Date	TC Holder	Type	Subject
2006-0140R2	2008-10-02	CTT Systems AB, JET AVIATION BASEL AG, LUFTHANSA TECHNIK AG, SR TECHNICS		Air Conditioning - Zonal Drying System Deactivation
2008-18-07	2008-10-02	BOEING	747	Main entry doors (MEDs)
2008-0181	2008-10-01	AIRBUS	A300, A300-600, A310	Nacelles / Pylons - Pylon Side Panels at Rib 8 - Inspection
2008-0182-E	2008-10-01	LANGE FLUGZEUGBAU GmbH	E1 Antares	DC-DC converter in the Hydraulic Management Module - Modification
2008-20-01	2008-10-01	LOCKHEED	382	Fuel tank systems - Fuel System Limitations (FSLs) and Critical Design Configuration Control Limitations (CDCCLs) features - Introduction of -
2008-0180	2008-09-30	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Fuselage - Wing-to-Fuselage & Main Landing Gear (MLG) Door Fairing Panel Grommets - Inspection / Replacement
2008-0170	2008-09-25	TURBOMECA	ARRIUS 2	Engine Fuel & Control - Lubrication Unit - Modification
2008-0178	2008-09-24	DASSAULT	FALCON2000, FALCON2000EX	Main Landing Gear - Shock Absorber Restrictor - Inspection / Repair
2006-0349R1	2008-09-23	EUROCOPTER	AS 332	Main Rotor - Main Rotor Head Spindles - Check / Replacement
2008-19-12	2008-09-22	HONEYWELL INTERNATIONAL INC	TFE731	Interstage Turbine Transition (ITT) Duct - Replacement
2008-18-09	2008-09-22	BOEING	747	Reserve fuel tanks - Modification