**Airworthiness Directives** 

Publ. number	Issue Date	TC Holder	Туре	Subject
2008-08-01	2009-01-08	EMBRAER	EMB120	APU Mounting Rods - Inspection / Rework / Replacement
2009-0005	2009-01-08	DOWTY PROPELLERS	R389/4-123-F/25, R389/4-123-F/26, R390/4-123-F/27	Propellers - Hub Assembly - Inspection
2009-0001	2009-01-08	AIRBUS	A330, A340	Wings - Center Wing - Frame (FR) 40 Rear Fitting Web - Inspection
2008-26-07	2009-01-08	MCDONNELL DOUGLAS	DC8	Inspections of the lower skin and stringers
2008-25-05	2009-01-08	MCDONNELL DOUGLAS	DC8	Program of Structural Inspections of Baseline Structure - Revision
2008-26-11	2009-01-07	PIPER	PA46	Stall Warning Heat Control Modification
2008-26-01	2009-01-07	AIR TRACTOR	AT250, AT300, AT301, AT302, AT400, AT401, AT402, AT602, AT802	Overturn Skid Plate - Installation/Modification
2009-0002	2009-01-07	TURBOMECA	ARRIEL 1	Engine - Reduction Gear Box Intermediate Pinion - Modification
2009-01-01	2009-01-07	EMBRAER	EMB135, EMB145	Landing Gear Electronic Unit (LGEU) - Replacement
2008-26-06	2009-01-06	ROLLS-ROYCE USA	AE3007	Engine Removal for Eddy Current Inspections (ECIs) on the High-Pressure Turbine (HPT) stage 2 wheels
2009-0003-E	2009-01-06	EUROCOPTER	AS 332, SA 330	Ice and Rain Protection - Main Rotor Blade De-Icing System - Modification / Inspection / Replacement
2008-26-04	2009-01-06	CESSNA	560	Airplane Flight Manual Revision, Minimum Airspeed placards Installation and Functional Test and Calibration of the Angle-of-Attack (AOA) system.

Biweekly 1-2009 Issued on 12/01/2009