



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0022-E	2009-02-06	AGUSTA	AB 206	Engine - Power Turbine Speed - Operational Limitation
2009-0020	2009-02-05	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
2009-0018	2009-02-05	FOKKER SERVICES	F27	Landing Gear - Main Landing Gear (MLG) Sliding Member End-Stop - Inspection / Installation
2007-0138R2	2009-02-03	EUROCOPTER	AS 350, AS 355	Tail Rotor - Tail rotor blades skin - Inspection / Repair
CF-2009-01	2009-02-03	BOMBARDIER	DHC-8	Broken Propeller De-ice Bus Bar causing Dual AC Generator Shutdown
2009-0019	2009-02-03	EUROCOPTER	AS 350	Rotors Flight Control - Collective Pitch Lever Locking Stud - Inspection / Repair
2009-0011	2009-01-28	EUROCOPTER	AS 350, EC 130	Time Limits/Maintenance Checks - Airworthiness Limitation - Revision
2009-0013	2009-01-28	SLINGSBY	T67	Flight Controls - Rudder Pedal and Ground Towing Damage - Inspection / Repair / Modification
2009-01-02	2009-01-27	BOEING	737	Support brackets of the air conditioning outlet extrusions between Body Station 360 and BS 907 -Inspection / Modification.
2009-02-03	2009-01-27	LYCOMING, Superior Air Parts, Inc., TELEDYNE CONTINENTAL	IO-360, LTSIO-360, TSIO-360	Reciprocating engines with a Precision Airmotive LLC or Bendix, RSA-5 or RSA-10 series, fuel injection servos - Inspection/Modification