



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0067-E	2009-03-20	AGUSTA	AB 206	[Corrected] Main Rotor - Pitch Horn Trunnion Bearing - Inspection / Replacement
2009-0066	2009-03-19	AIRBUS	A380	Pneumatic - Overheat Detection System - Inspection
2006-0334R1	2009-03-19	THALES COMMUNICATIONS		Communications - Thales Communications VHF Data Radio - Modification
2008-03-01R2	2009-03-19	EMBRAER	ERJ170	Full Authority Digital Engine Control (FADEC) Software Version - Replacement
2009-06-02	2009-03-18	BOEING	747	Widespread fatigue and skin cracks at the shear tie end fastener locations of the fuselage frames - Inspection/ Repair.
CF-2008-14	2009-03-18	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Air Driven Generator Power Centre Contactors - Identification and Removal from Service
2009-05-08	2009-03-17	FREEFLIGHT SYSTEMS		2101 I/O Approach Plus Airborne GPS Navigation System - Software Upgrade
CF-2009-09	2009-03-17	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Fuel System Safety - Hydraulic System Overheat Inside the Fuel Tank
2007-0071R1	2009-03-16	APEX	DR 400	Wings - Main spar and fabric covering - Reinforcement / Modification / Inspection.
CF-2009-11	2009-03-16	BOMBARDIER	DHC-8	Main Landing Gear Forward Stabilizer Brace P/N 46401-7 Inspection
2009-0065	2009-03-13	EUROCOPTER DEUTSCHLAND	EC 135, EC 635	Fuselage - Rear Structure / Tail Boom - Pre-Flight Check / Inspection
2009-0057	2009-03-13	AIRBUS	A310	Wings - Centre Wing Trellis Boom Drainage Holes & Frame 40 Upper Corner Fitting - Inspection / Repair
2009-0062	2009-03-13	RUAG Aerospace Services, GmbH	228	Main Landing Gear - Identification / Replacement of the Main Landing Gear Stub Axle
2009-0058	2009-03-13	AIRBUS	A310	Fuselage - Aft Fuselage Lower Tail Plane Cut-out - Inspection
CF-2009-08	2009-03-13	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Cabin Pressure Control (CPC) Units and Cabin Pressure Control Panel (CPCP) Deficiency
CF-2009-10	2009-03-13	BELL	206, 407, 427	Cyclic Control Lever Assembly Installation
2007-0053R2	2009-03-13	AIRBUS	A310	Fuselage / Stabilisers / Wings - Structural Fatigue - Inspection / Modification
2009-0055	2009-03-13	AIRBUS	A300-600, A300-600ST BELUGA, A310	Electrical Power - Engine Feeder Harness - Inspection & Nacelles/Pylons - GE CF6-80C2 Pylon Forward Pyramid - Inspection
2009-02-06	2009-03-13	BOEING	737	Fuselage Frame and Frame reinforcement - Inspections, Related Investigative and Corrective Actions - Terminating Action
2009-04-12	2009-03-12	BOEING	767	Emergency Escape System Separation Link Assembly - Replacement
CF-2008-27R1	2009-03-12	VIKING AIR LTD	DHC-7	Fluorescent Lighting System - Lamp Holder Overheating



Publ. number	Issue Date	TC Holder	Type	Subject
2009-05-11	2009-03-12	BOEING	777	Airplane Flight Manual (AFM) - Cold Weather Conditions
2009-0061	2009-03-12	AIRBUS	A340	Landing Gear - Main Landing Gear (MLG) Lower Articulation Link - Replacement
2009-0064	2009-03-12	AIRBUS	A330, A340	Fire Protection - Fire Extinguishing System - Replacement / Modification
2009-0056	2009-03-11	AIRBUS	A340	Exhaust - Thrust Reverser "J-Ring" at 6 and 12 o'clock Beam - Inspection
2009-0060	2009-03-11	PILATUS	PC12	Nose Gear - Torque Tube of the Nose Wheel Steering - Replacement / Limitations
2009-0063	2009-03-11	AIRBUS	A340	[Corrected] Exhaust - Thrust Reverser - Inspection / Adjustment
2009-0059	2009-03-11	AVIA PROPELLER s.r.o.	V410, V500, V503, V506, V520	Propeller - Repetitive Inspections of the Propeller Blades