



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0116	2009-05-29	FOKKER SERVICES	F28	Fuel System - Crossfeed Valve Actuator - Replacement
2009-0094	2009-05-29	AIRBUS	A300, A300-600	[Correction] Fuselage / Wings - Frame 40 Forward Fitting between Stringers 32 and 33 - Inspection / Repair
2009-0115	2009-05-29	AIRBUS	A340	Power Plant - Forward Engine Mount Thrust Links - Replacement
CF-2009-24	2009-05-29	BOMBARDIER	CL600 2B16	Air Driven Generator (ADG) - Strut Cracking
2009-0101	2009-05-28	BOEING	747, 757, 767	Indicating / Warning - Overspeed Warning System - Modification
2009-0114	2009-05-28	DOWTY PROPELLERS	R408/6-123-F/17	Propellers - Backplate Assembly - Sealant Application
CF-2009-22	2009-05-28	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Landing Gear Alternate Extension System (AES) - Valve Clevis Damage
CF-2009-23	2009-05-28	BOMBARDIER	CL600 2B19, CL600 2C10, CL600 2D15, CL600 2D24	Passenger Door Corrosion - Removal
2009-0113	2009-05-27	AIRBUS	A380	Wings - Movable Flap Track Fairing number 4 (MFTF #4) - Inspection / Replacement
2009-11-03	2009-05-27	LOCKHEED	382	Wings - Barrel Nuts - Inspection / Replacement
CF-2009-21R1	2009-05-26	BOMBARDIER	CL600 1A11, CL600 2A12, CL600 2B16	Nose Landing Gear Selector Valve and Nose Gear Door Selector Valve End Caps - Incorrect Assembly
2006-0208R1	2009-05-26	FOKKER SERVICES	F28	Fuel Tank Safety - Fuel Airworthiness Limitations - Implementation
2006-0207R1	2009-05-26	FOKKER SERVICES	F27	Fuel Tank Safety - Fuel Airworthiness Limitations - Implementation
2009-04-06	2009-05-26	BOEING	747	[Correction] Fuselage Aft Pressure Bulkhead Inspection/Repair
CF-2005-12R1	2009-05-20	BOMBARDIER	BD100 1A10	AFM Change - Failure of Proximity-Sensor Electronic Unit
2009-10-01	2009-05-20	PRATT & WHITNEY	JT9D	[Correction] High-Pressure Turbine (HPT) Vane Assemblies - Removal; and HPT Air Seal Assembly - Inspection
2009-11-02	2009-05-20	CFM INTERNATIONAL	CFM56-2, CFM56-3, CFM56-5A, CFM56-5B, CFM56-5C, CFM56-7B	High-Pressure Compressor (HPC) 4-9 Spools Improperly repaired by Propulsion Technology LLC (PTLLC)
2009-10-09	2009-05-19	CESSNA	150, 152, A150, A152, F150, F152, FA150, FA152	Flight Controls - Rudder stops modification and Acrobatic Manoeuvres - Installation / Limitations
2009-0112	2009-05-18	TURBOMECA	ARRIEL 1, ARRIEL 2	Engine - Module M04 (Power Turbine) Power Turbine Blades - Life Limit / Replacement