



| Publ. number | Issue Date | TC Holder | Type | Subject |
|--------------|------------|--|---|---|
| 2009-0124 | 2009-06-12 | AGUSTA, EUROCOPTER, EUROCOPTER DEUTSCHLAND | A109, AB 139, AW 139, AS 332, AS 350, AS 355, AS 365, EC 155, EC225, SA 330, SA 360, BK 117, EC 135 | Equipment / Furnishings - Lifesaving Systems' D-Lok Hook of the Rescue Hoist - Inspection / Replacement |
| 2009-0125-E | 2009-06-12 | EUROCOPTER | AS 365, SA 365, SA 366 | Fuselage - Frame N. 9 - Inspection / Repair |
| 2009-0122 | 2009-06-10 | EUROCOPTER | AS 332, AS 350, AS 355, AS 365, EC 120, EC 130, EC 155, EC225, SA 330 | Equipment / Furnishings -Load Release Units - Inspection / Modification / Limitation |
| 2009-0123-E | 2009-06-10 | EUROCOPTER DEUTSCHLAND | BK 117 | Airworthiness Limitations - Tail Rotor Intermediate Gear Box Bevel Gear - Inspection / Reduced Life Limit |
| 2009-0121-E | 2009-06-09 | BAE SYSTEMS (OPERATIONS) LTD | HP 137 JETSTREAM MK 1, JETSTREAM200, JETSTREAM3100, JETSTREAM3200 | Landing Gear - Main Landing Gear Radius Rod - Inspection / Replacement |
| 2009-0118-CN | 2009-06-05 | TURBOMECA | ASTAZOU | Cancellation of AD F-2005-047 - Civil use |
| CF-2009-26 | 2009-06-05 | BOMBARDIER | DHC-8 | Inadvertent Single Spoiler Deployment |
| 2009-0119 | 2009-06-04 | EUROCOPTER DEUTSCHLAND | BK 117 | Tail Rotor Drive - Tail Rotor (T/R) Drive Shaft - Inspection |
| 2009-0120 | 2009-06-04 | PZL SWIDNIK | PZL W-3A | Main Rotor - Main Rotor (M/R) Blade Attachment Points - Inspection / Replacement |
| 2009-10-06 | 2009-06-04 | BOEING | 747 | Fuselage - Section 41 Upper Deck Floor Beam Upper Chords - Inspection / Repair |
| 2009-11-13 | 2009-06-04 | LEARJET | 45 | Engine Nacelle Tubing and Hydraulic Pump Casing - Inspections / Repair / Rework |
| 2009-11-11 | 2009-06-04 | MCDONNELL DOUGLAS | MD90 | Fuel Level Float/Pressure Switch in-line Fuses and Wire Protection- Installation |
| 2009-10-12 | 2009-06-03 | BOEING | 747 | Equipment & Furnishings - Escape Slides/Rafts Inflation Systems - Modification |
| 2009-0117-E | 2009-06-02 | TURBOMECA | ARRIEL 1 | Engine - Module M05 (Reduction Gear Box) Lubrication Duct - Inspection / Repair |
| 2009-11-05 | 2009-06-02 | AIR TRACTOR | AT400, AT402, AT502, AT503, AT602, AT802 | [CORRECTED] - Powerplant - Engine Mounts - Inspection / Repair / Replacement |
| 2009-05-02 | 2009-06-02 | EMBRAER | EMB135, EMB145 | Airworthiness Limitations Items (ALI) - Modification |
| 2009-11-06 | 2009-06-01 | M7 AEROSPACE | SA226, SA227 | Wires, Components and Tube Assemblies - Inspection/ Repair / Replacement |