



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0198-E	2009-09-04	AGUSTA	AB 139, AW 139	Fuselage - Tail Boom - Inspection
2009-0196	2009-09-04	328 Support Services GmbH	328-100	Engine Controls - Power Lever Control Box - Modification
CF-2009-36	2009-09-04	BOMBARDIER	CL600 2B19	Stick Pusher Capstan Shaft Failure
2009-0197-E	2009-09-03	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Landing Gear - Nose Landing Gear - Inspection / Replacement
CF-2009-35	2009-09-02	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Angle of Attack Transducer - Heating Element Degradation and Inaccurate Calibration
2009-0194	2009-09-01	328 Support Services GmbH	328-100, 328-300	Wings - Lower Inner Panel - Inspection / Repair / Modification
2009-0195	2009-08-31	AIRBUS	A330, A340	Navigation - Airspeed Pitot Probes - Replacement
2009-0187	2009-08-31	ROLLS-ROYCE PLC	RB211 TRENT 700, RB211 TRENT 800, RB211-524, RB211-535	Engine - Front Combustion Liner Head Section - Inspection / Replacement
2009-0192	2009-08-28	AIRBUS	A340	Time Limits and Maintenance Checks - Airworthiness Limitations Section Part 1 - Amendment
2009-0191	2009-08-28	AIRBUS	A330	Time Limits and Maintenance Checks - Airworthiness Limitation Section Part 1 - Amendment
2009-0193	2009-08-27	THIELERT AIRCRAFT ENGINES	TAE125	Propellers/Propulsion - Vibration Isolator of the Propeller's Constant Speed Unit - Installation
CF-2009-34	2009-08-27	BELL CANADA	206	Main Rotor Pitch Horn Bearing - Inspection/Replacement
2009-0188	2009-08-26	AIRBUS	A300-600	Fuselage - Frame bases between FR48 to FR53 - Reinforcement
2009-0189	2009-08-26	AIRBUS	A300	Engine Exhaust - Thrust Reverser - Modification
2009-0190	2009-08-26	EUROCOPTER	EC 120, EC 130	Equipment / Furnishings - Emergency Floatation Gear - Inspection
2006-0111R1	2009-08-26	AIRBUS	A310	Flight Controls - Flap Transmission Shaft - Inspection / Repair
CF-2009-28R1	2009-08-25	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Flight Controls - Elevator Power Control Unit (PCU) Centering Mechanism - Replacement
BR-2009-08-03	2009-08-24	EMBRAER	EMB135, EMB145	Airworthiness Limitation Section (ALS) - Revision
2009-0180-E	2009-08-24	GULFSTREAM	GIV, GV-SP	Airborne Auxiliary Power - Auxiliary Power Unit (APU) Enclosure (Firewall) - Inspection / Limitation
2009-0186	2009-08-24	AIRBUS	A310	Wings - Wing Tip Fences - Inspection / Repair / Replacement