



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0204	2009-09-30	AIRBUS	A330, A340	Power Plant - Engine Mount Link Pin Retention Bolts - Inspection / Replacement
2009-0206	2009-09-30	BAE SYSTEMS (OPERATIONS) LTD	BAE146	Flight Controls - Airbrake Lever Detent Mechanism - Modification
2009-0205	2009-09-30	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Flight Controls - Aileron Interconnect Cable Pulley Guards - Installation
2009-0207	2009-09-30	EUROCOPTER DEUTSCHLAND	EC 135, EC 635	Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment
US-2009-19-04	2009-09-29	MCCAULEY PROPELLER SYSTEMS	5JFR36C	Propeller Blades - C-5963 Split Retainers - Inspection / Replacement
CF-2009-10R1	2009-09-29	BELL CANADA	206, 407, 427	Rotors Flight Control - Cyclic Control Lever Assembly Installation - Inspection
US-2009-19-05	2009-09-28	BOEING	747	Fuselage Frames in Section 41 - Inspection / Repair
2009-0203-E	2009-09-28	AIRBUS	A380	Water / Waste - Potable Water Circulation Pump and Treatment Module - Test / Inspection
US-2009-19-07	2009-09-24	TELEDYNE CONTINENTAL	IO-470, IO-520, IO-550, IOF-550, O-470, TSIO-470, TSIO-520	Engine - EQ3 Cylinders - Inspection / Replacement
US-2009-19-02	2009-09-23	BOEING	737	Rudder Feel- & Centering Unit Inspection / Modification
2009-0202-E	2009-09-22	AIRBUS	A330, A340	CORRECTED: Navigation - Pitot Probe Quick-Disconnect Union - Torque Check
BR-2009-09-01	2009-09-21	EMBRAER	EMB500	RH and LH Elevators Mass Balance Fastener Nuts - Replacement