



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0247	2009-11-13	EUROCOPTER	AS 365, EC 155, SA 365, SA 366	Time Limits / Maintenance Checks, Tail Rotor Drive - Tail Gearbox (TGB) Oil Level and Tail Rotor Pitch Control Rod Bearing - Inspection
US-2009-19-06	2009-11-12	BOEING	747	Sensitive Security Airworthiness Directive - Refer to your local Airworthiness Authority for further information
US-2009-23-10	2009-11-10	BOEING	737	Wings - Outboard Trailing Edge Flaps - Carriage Spindles - Inspection / Repair
2009-0245-E	2009-11-10	TURBOMECA	ARRIEL 1	Engine - Module M05 (Reduction Gear Box) Lubrication Duct - Inspection / Repair
2009-0243	2009-11-10	ROLLS-ROYCE PLC	RB211 TRENT 700, RB211 TRENT 800, RB211-524, RB211-535	Engine - Front Combustion Liner Inner Wall - Inspection
CF-2009-38	2009-11-10	BOMBARDIER	BD100 1A10	Left Hand Baggage Bay Sidewall Heater - Excessive Heat
US-2009-23-03	2009-11-10	HAWKER BEECHCRAFT CORPORATION	1900	Forward, Vertical, Aft Flanges - Left and Right Wing Rear Spar Lower Caps - Inspection / Repair
2007-0226R1	2009-11-10	ATR	ATR42, ATR72	Fuel - Fuel Tank System Wiring & Sensors - Modification/Replacement - Fuel Tank Safety
US-2009-10-09R1	2009-11-10	CESSNA	150, 152, A150, A152, F150, F152, FA150, FA152, FRA150	Flight Controls - Rudder Stops Modification / Acrobatic Manoeuvres Limitations
2009-0246	2009-11-10	TURBOMECA	ARRIEL 2	Engine Fuel & Control - Hydro HMU Acceleration Control Axle - Inspection and Lubrication
2007-0109R1	2009-11-09	TURBOMECA	ARRIEL 2	Engine - Module M03 (Gas Generator) - Turbine Blade Borescope Inspection/Replacement
2009-0244	2009-11-09	ROLLS-ROYCE PLC	RB211-535	Engine - Low Pressure (LP) Turbine Stage 1, 2 and 3 Discs - Inspection
US-2009-18-10	2009-11-05	BOEING	707, 720	Wings - Body Terminal Fittings - Inspection / Repair
US-2009-21-01	2009-11-05	BOEING	737	Fuselage - Aft Fuselage Skin - Inspection / Repair
2009-0240	2009-11-05	AIRBUS	A330	Power Plant - Forward and Aft ward Mount Pylon Bolts - Inspection / Replacement
2009-0241-E	2009-11-05	EUROCOPTER	AS 365	Navigation - Vertical Gyro Unit Data Output - Operational Limitation / Operational procedure
CF-2009-39	2009-11-04	BOMBARDIER	CL600 1A11, CL600 2A12, CL600 2B16	Hydraulic Accumulators - Screw Cap/End Cap Failure



Publ. number	Issue Date	TC Holder	Type	Subject
US-2009-22-14	2009-11-04	BOEING	747	Equipment/Furnishings - Electrical/Electronic Units in Main Equipment Center - Installation
US-2009-23-01	2009-11-03	HAWKER BEECHCRAFT CORPORATION	1900	Landing Gear - Left and Right Main Landing Gear (MLG) Actuators - Inspection / Replacement
US-2009-21-07	2009-11-03	GENERAL ELECTRIC	CF6	Thrust and Thrust Control - GE CF6-80C2 Series Turbofan Engines - Inspection / Replacement
2009-0229	2009-11-03	TECNAM	P2002	Retractable Landing Gear System - Inspection
2009-0239-E	2009-11-03	DG-FLUGZEUGBAU	DG-500 M, DG-800 A	Starting - Starter Ring Gears - Inspections / Replacement
US-2008-10-07R1	2009-11-03	BOEING	747	Fuel Tank Systems - Airworthiness Limitations (AWLs) - Revision