



Publ. number	Issue Date	TC Holder	Type	Subject
2009-0243R1	2009-11-26	ROLLS-ROYCE PLC	RB211 TRENT 700, RB211 TRENT 800, RB211-524, RB211-535	Engine - Front Combustion Liner Inner Wall - Inspection
2009-0251-E	2009-11-25	FIRE FIGHTING ENTERPRISES LTD	Portable Halon 1211 (BCF) Fire Extinguishers	Fire Protection - Portable Fire Extinguishers - Identification / Replacement
CF-2009-42	2009-11-25	BOMBARDIER	CL215 1A10, CL215 6B11	Hydraulic Accumulators - Screw Cap/End Cap Failure
CF-2009-40	2009-11-20	BOMBARDIER	DHC-8	Fuel Tank - Removal of Non-Conforming Springs from the Collector Tank Flapper Valves
2009-0249	2009-11-20	PILATUS	PC12	Navigation - Air Data, Attitude and Heading Reference System (ADAHRS) - Modification/Replacement
BR-2006-11-01R4	2009-11-20	EMBRAER	ERJ190	Engine Low Pressure Check Valve (LPCV) - Periodic Replacement
CF-2009-41	2009-11-19	BELL CANADA	206	Tailboom Attachment Fitting
US-2009-24-52	2009-11-19	TELEDYNE CONTINENTAL	GTSIO-520, IO-240, IO-360, IO-470, IO-520, IO-550, IOF-240, IOF-550, O-240, O-470, TSIO-360, TSIO-470, TSIO-520, TSIO-550, TSIOL-550	Hydraulic Valve Lifters - Identification / Replacement
US-2009-24-51	2009-11-18	TELEDYNE CONTINENTAL	GTSIO-520, IO-240, IO-360, IO-470, IO-520, IO-550, IOF-240, IOF-550, O-240, O-470, TSIO-360, TSIO-470, TSIO-520, TSIO-550, TSIOL-550	SUPERSEDED BY FAA EMERGENCY AD 2009-24-52
US-2009-22-06	2009-11-18	INTERNATIONAL AERO ENGINES	V2500, V2500-()5	High-Pressure Compressor (HPC) Stage 9-12 Disc Assembly
CF-2007-13R2	2009-11-17	BELL CANADA	206	Power Turbine RPM Steady State Operation Avoidance