



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0063-E	2010-04-01	ATR	ATR72	Flight Controls - Rudder Pedal Rods - Inspection / Replacement
2010-0064-E	2010-04-01	EUROCOPTER	AS 365, SA 365, SA 366	Fuselage - Frame No. 9 - Inspection / Repair
2010-0062	2010-03-31	FIRE FIGHTING ENTERPRISES LTD	Halon 1211 (BCF) Fire Extinguishers	Fire Protection - Halon 1211 Fire Extinguishers - Identification / Replacement
2010-0061	2010-03-31	ATR	ATR42, ATR72	Fire Protection - Halon 1211 Fire Extinguishers - Identification / Replacement
2010-0065-E	2010-03-31	GROB	G120	Wings - Right Hand (RH) and Left Hand (LH) Flap Ribs - Inspection
US-2010-07-02	2010-03-30	HONEYWELL INTERNATIONAL INC	RNZ-850() INU, RNZ-851() INU	Navigation - Integrated Navigation Units (INUs) - Aircraft Flight Manual (AFM) Revision / Inspection
2010-0045	2010-03-30	EUROCOPTER DEUTSCHLAND	BK 117	[2nd Correction] Rotor Flight Controls - Upper Control Bellcrank Assembly - Modification / Inspection / Replacement
2010-0058	2010-03-30	EUROCOPTER DEUTSCHLAND	BK 117, EC 135, EC 635	Rotor Flight Controls - Tail Rotor, Cyclic and Collective Control Levers - Inspection / Repair
US-2010-06-10	2010-03-30	BOEING	767	Fuel - Fuel Quantity Indicating System (FQIS) - Installation / Airworthiness Limitations (AWL) Revision
US-2010-06-17	2010-03-30	BOEING	757	Oxygen - Low-Pressure Flex-Hoses - Inspection / Installation
2010-0056	2010-03-29	AIRBUS	A340	Wings - Inner Ailerons - Inspection
2010-0060	2010-03-29	ROLLS-ROYCE DEUTSCHLAND	Tay	Engine - Low Pressure Turbine Discs Stage 2 and 3 - Inspection/Replacement
2010-0059-E	2010-03-26	AGUSTA	A119, AW119	Tail Rotor Drive - Tail Rotor Gearbox Assembly - Inspection / Replacement / Re-identification
2010-0043R1-E	2010-03-26	EUROCOPTER	AS 332	Hydraulic Power - Hydraulic Pumps - Identification / Replacement
2010-0057	2010-03-26	AGUSTA	AB 212	Main Rotor - Main Rotor Blade - Inspection
2010-0044	2010-03-25	AIRBUS	A340	[Correction] Exhaust - Thrust Reverser Actuation System Doors - Replacement
2010-0054	2010-03-25	328 Support Services GmbH	328-100, 328-300	Flight Controls - Tab-to-Actuator Linkage - Reduced Inspection Intervals
2010-0055	2010-03-25	TURBOMECA	MAKILA 2	Engine Fuel & Control - Digital Engine Control Unit - Replacement
2010-0051	2010-03-25	VULCANAIR	P68	Structures - Wing Safe Life Fatigue Limits / Wing & Stabilizers Structures - Implementation / Inspection
2010-0049	2010-03-24	EUROCOPTER DEUTSCHLAND	BK 117, BO 105	[Correction] Rotors Flight Control - Cyclic-Stick Locking Device - Modification
US-2010-06-13	2010-03-23	LEARJET	45	Flight Controls - Flap Actuators - Inspection
CF-2010-09	2010-03-23	PRATT & WHITNEY CANADA	PW305	Engine Impeller in-service Life Reduction



Publ. number	Issue Date	TC Holder	Type	Subject
US-2010-06-16	2010-03-23	BOEING	767	Fuselage - Fuselage Skin - Inspection
US-2010-05-13	2010-03-23	BOEING	737	[Correction] Fuselage - Fuselage Skin - Inspection
2010-0050	2010-03-23	MD HELICOPTER	MD900	Main Rotor - Main Rotor (MR) Blade Retention Bolts - Inspection / Replacement (Life Limit)
2010-0052-E	2010-03-23	EUROCOPTER	AS 365, EC 155	Equipment / Furnishings - External Life Raft Mooring Line Attachment - Inspection / Rework
2008-0058R1	2010-03-22	AIRBUS	A300-600, A300-600ST BELUGA	Flight Controls - Spoiler Actuators - Life Limitation
CF-2010-08	2010-03-22	BOMBARDIER	DHC-8	Electrical Power - AC Wiring Harness Chafing on Centre Wing Lower Flap Shroud
US-2010-06-18	2010-03-22	INTERNATIONAL AERO ENGINES	V2500-()5, V2500-A1	Engines - Vortex Reducers - Inspection
US-2010-06-15	2010-03-22	GENERAL ELECTRIC	CF6-45, CF6-50	Engines - Low-pressure Turbine (LPT) Stage 3 Disks - Inspection
US-2010-06-11	2010-03-22	HONEYWELL INTERNATIONAL INC	TFE731	Turbofan Engines - Low-pressure Compressor Rotor (LPCR) Discs - Removal