



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0166	2010-08-06	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
2010-0165	2010-08-05	AIRBUS	A318, A319, A320, A321	Oxygen System - Passenger Oxygen Masks - Identification / Modification / Replacement
2010-0164	2010-08-05	AIRBUS	A318, A319, A320, A321	Stabilizers - Rudder Side Shell Skin - Inspection
2010-0163	2010-08-04	CERVA, WASSMER	CE, WA21	Flight Controls - Reducing box - Inspection / Replacement
2010-0101R1	2010-08-04	TURBOMECA	ARRIEL 1	Engine - Module M03 (Gas Generator) - Post-TU347 Second Stage Turbine Disc - Reduced Life Limit
2010-0008R1	2010-08-04	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - Intermediate Pressure Shaft Coupling Splines - Inspection
2010-0162	2010-08-04	BAE SYSTEMS (OPERATIONS) LTD	JETSTREAM3100, JETSTREAM3200	Time Limits and Maintenance Checks - Main Landing Gear Radius Rod Mounting Shaft Assembly - Safe Life Limit / Replacement
2010-0100R1	2010-08-04	EUROCOPTER	AS 365, SA 365	Navigation - Vertical Gyro Unit Data Output - Operational Limitation / Operational procedure / Reinforcement
2010-0161	2010-08-03	TURBOMECA	TM 333	Engine - Maintenance Manual - Airworthiness Limitation Section Update
2010-0158	2010-08-03	FOKKER SERVICES	F28	Fuel - Crossfeed Valve System and Fire Shut-off Valve System - Modification
2010-0157	2010-08-03	FOKKER SERVICES	F27	Fuel - Fuel Quantity Probe & Wiring Installation - Inspection / Modification [Fuel Tank Safety]
2010-0156	2010-08-03	FOKKER SERVICES	F28	Fuel - Outer Wing Upper Skin Panel Reinforcement Structure - Inspection / Rework [Fuel Tank Safety]
2010-0159	2010-08-03	FOKKER SERVICES	F28	Fuel - Wing Tank Overflow Valve Sense Line- & Wiring Conduit Hose Attachments - Inspection / Modification [Fuel Tank Safety]
2009-0081R1	2010-07-30	AIRBUS	A300, A300-600	Wings - Main Landing Gear (MLG) Rib 5 Attachment Fitting Lower Flange - Inspection / Repair
2010-0160-E	2010-07-30	AIRCRAFT INDUSTRIES	L-13 (Blanik)	Wing - Wing Main Spar - Inspection / Operational Limitation / Operational Records Check
US-2010-15-10	2010-07-29	PIPER	PA28, PA28R, PA28RT, PA28S, PA32, PA32R, PA32RT, PA32S, PA34, PA44	Flight Controls - Control Wheel Shaft - Inspection
US-2010-13-07	2010-07-29	PIPER	PA32R, PA46	[Correction] Engine Exhaust V-band Coupling Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0155	2010-07-29	DIAMOND	DA42, DA42M	Landing Gear - Main Landing Gear Damper-to-Trailing Arm Joints - Inspection / Replacement
US-2010-15-08	2010-07-28	BOEING	737	Wings - Carriage Spindles - Inspection / Replacement
2010-0150	2010-07-27	SIKORSKY	S76	Power Train - Main Rotor Electric Rotor Brake (ERB) System - Deactivation / Modification
2010-0153	2010-07-27	EUROCOPTER DEUTSCHLAND	BO 105	Time Limits / Maintenance Checks - Main Rotor Blades with Bolted Lead Inner Weight - Life Limitation
BR-2010-06-03	2010-07-27	EMBRAER	EMB135, EMB145	SUSPENDED - REFERENCE EMBRAER SERVICE BULLETIN TO BE REVISED/CORRECTED
2010-0152	2010-07-26	INTERTECHNIQUE	Oxygen masks	Equipment and Furnishing - Oxygen Mask Regulator - Modification