



Publ. number	Issue Date	TC Holder	Type	Subject
GA8-3-Amdt2	2010-08-20	GIPPSLAND	GA8	Forward Cargo Door Slide - Inspection
US-2010-14-06	2010-08-20	BOEING	737	Oxygen - Oxygen Masks - Inspection
2010-0176	2010-08-20	PILATUS	PC6	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment / Implementation
US-2010-16-06	2010-08-20	BOEING	737	Oxygen - Crew Oxygen System - Inspection
2010-0172-E	2010-08-19	MD HELICOPTER	MD900	[Correction] Main Rotor - Main Rotor (MR) Lower Hub Assembly - Inspection
US-2010-17-05	2010-08-19	BOEING	737	Fuel - Power Control Relays - Replacement
US-2010-17-03	2010-08-19	BOEING	767	Wings - Wire Bundle Clamp & Tetrafluoroethylene Sleeve - Replacement / Installation
2010-0175	2010-08-18	AIRBUS	A300-600, A300-600ST BELUGA, A310	Fuel - Fuel Level Sensor Amplifier (FLSA) and Multi Tank Indicator (MTI) Wiring - Replacement
2010-0174	2010-08-17	AIRBUS	A330	Time Limits and Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment
2010-0171	2010-08-17	AGUSTA	AB 412, AB 412EP	Fuselage - Wire Strike Protection System (WSPS) - Upper Cable Cutter- Inspection / Replacement
2010-0173	2010-08-17	AIRBUS	A330	Fuselage - Fuselage Internal Structure at Frame 39.1 - Inspection
2010-0170-E	2010-08-17	SIKORSKY	S92	Main Rotor Drive - Main Gearbox (MGB) - Inspection / Replacement
2009-0088R1	2010-08-17	CFM INTERNATIONAL	CFM56-5B	[Correction] Engine - High Pressure Compressor (HPC) - Inspection / Replacement
US-2010-16-04	2010-08-16	BOEING	767	Oxygen - Flex-Hose - Inspection / Replacement
2009-0073R1	2010-08-16	ROLLS-ROYCE PLC	RB211 TRENT 500, RB211 TRENT 700, RB211 TRENT 800, RB211-524	[Correction] Engine - High Pressure (HP) Compressor Stage 1 to 4 Rotor Discs and HP Compressor Rotor Shafts - Inspection
2010-0154	2010-08-13	EUROCOPTER DEUTSCHLAND	BK 117, EC 135, EC 635	Optional Equipment - External Mounted Hoist System - Visual Check / Replacement
2010-0169	2010-08-13	328 Support Services GmbH	328-100, 328-300	Equipment & Furnishings - Flight Compartment Door Locking Device - Replacement
CF-2010-25	2010-08-12	BOMBARDIER	CL600 2B16	Electrical Power - AC Electrical Load Distribution - Inspection
57-10-06-18	2010-08-12	GULFSTREAM (GALP)	G200, GALAXY	Inspection and replacement of cracked nuts in specific area



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0167	2010-08-11	AIRBUS	A380	Fire Protection, Nacelles / Pylons - Wing Pylon Interface / Double-Wall Fuel Pipe Assembly - Inspection
2010-0100R1	2010-08-11	EUROCOPTER	AS 365, SA 365	[Correction] Navigation - Vertical Gyro Unit Data Output - Operational Limitation / Operational procedure / Reinforcement
2010-0168	2010-08-11	AIRBUS	A380	Doors - Wing Landing Gear Door (WLGD) Hinge and Rods - Inspection / Replacement
US-2010-16-03	2010-08-11	MCDONNELL DOUGLAS	MD11	Engines - Ice and Rain Protection - Airplane Flight Manual (AFM) Revision
US-2010-16-05	2010-08-11	BOEING	747	Oxygen - Crew Oxygen System - Inspection / Replacement
US-2010-16-08	2010-08-10	SCHWEIZER	269D	Rotor - Scroll ousing Blade Containment Shielding Kit - Installation
CF-2010-24	2010-08-09	BOMBARDIER	CL600 2B19	Hydraulic Accumulators - Screw Cap/End Cap Failure
BR-2010-06-01R1	2010-08-09	EMBRAER	ERJ170	Bulkhead Drill Marks - Inspection
US-2009-15-16R1	2010-08-09	MCDONNELL DOUGLAS	DC9, MD88, MD90	Flight Deck Door - Modification
BR-2010-08-01	2010-08-09	EMBRAER	EMB500	Flow Control Shutoff Valve (FCSOV) - Replacement