



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0216-E	2010-10-29	EUROCOPTER DEUTSCHLAND	BO 105	[Correction] Main Rotor - Main Rotor Blade Erosion Protective Shell - Inspection / Replacement
2010-0226	2010-10-29	PIAGGIO	P166, P180	Propellers - Blades - Inspection / Repair
US-2010-21-16	2010-10-29	MCDONNELL DOUGLAS	MD90	Auxiliary Hydraulic Power System - Inspection / Correction / Modification
CF-2010-35	2010-10-29	BOMBARDIER	CL600 2C10, CL600 2D15	Hydraulic Accumulators - Screw Cap/End Cap Failure
2009-0122R1	2010-10-27	EUROCOPTER	AS 332, AS 350, AS 355, AS 365, EC 120, EC 130, EC 155, EC225, SA 330	Equipment / Furnishings -Load Release Units - Inspection / Modification / Limitation
2010-0210	2010-10-27	AIRBUS	A318, A319, A320	[Correction] Equipment / Furnishings - Off-wing Escape Slide Enclosure - Modification
2010-0223	2010-10-26	EUROCOPTER DEUTSCHLAND	BO 105	Main Rotor Drive - Main Gearbox - Inspection
2008-0173R1	2010-10-22	AIRBUS	A330, A340	Electrical Power / Airborne Auxiliary Power - Auxiliary Power Unit (APU) Generator - Inspection / Modification
2010-0222-E	2010-10-22	AGUSTA	A109	Tail Rotor Drive - Tail Rotor Special Hub Plug - Inspection
2010-0218	2010-10-22	AIRBUS	A380	Wings - Inner Leading Edge Droop Nose 1 Sidestay Bracket - Inspection / Replacement
2010-0219	2010-10-21	SCHWEIZER	269A, 269B, 269C, 269D	Doors - Door Hinge Plates - Modification / Replacement
2010-0217	2010-10-21	FOKKER SERVICES	F28	Fuel - Fuel Quantity Indication System - Inspection / Modification [Fuel Tank Safety]
CF-2010-36	2010-10-21	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Main Landing Gear Door - Fairing Seal Interference
US-2010-22-01	2010-10-21	BOEING	767	Nacelles/Pylons - Nacelles Struts - Upper Link Fuse Pin - Inspection / Modification
US-2010-21-13	2010-10-20	MCDONNELL DOUGLAS	DC10	Fuel - Left and Right Wing-to-fuselage Transition - Installation
BR-2010-10-01	2010-10-20	EMBRAER	ERJ170	Airworthiness Limitation Section (ALS) of Embraer ERJ 170 Revision - New and/or Modified Structural Inspections
US-2010-21-18	2010-10-20	AVIATION ENTERPRISES, CESSNA	STC SA02055AT, STC SA02056AT, STC SA02307AT, STC SA02308AT, 336, 337, F337, FT337, M337, P337, T337	Wings - Upper Wings Skin - Inspection / Repair
2010-0165	2010-10-20	AIRBUS	A318, A319, A320, A321	[Correction] Oxygen System - Passenger Oxygen Masks - Identification / Modification / Replacement
US-2010-21-19	2010-10-20	LEARJET	45	Fire Protection - Fire Extinguisher Discharge Tubes - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
US-2010-19-03	2010-10-18	BOEING, PATS Aircraft, LLC	737, EASA.IM.A.S.01751, ST00936NY-D	Fuel - Auxiliary Fuel Tanks - Modification
2010-0212	2010-10-18	CFM INTERNATIONAL	CFM56-5B	Engine - Fan Blade - Replacement
CF-2010-34	2010-10-18	BOMBARDIER	CL600 2C10, CL600 2D15, CL600 2D24	Flight Controls - Horizontal Stabilizer Trim Actuator - Rubber Bull Gear Wheel Material Hardness out of Specification
US-2010-21-17	2010-10-18	PRATT & WHITNEY	JT8D	Propellers/Propulsion - Fan Blades - Overhaul