



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0244	2010-11-26	BOEING	737	Exhaust - Thrust Reverser Inner Wall - Inspection / Repair
2010-0248	2010-11-26	EUROCOPTER DEUTSCHLAND	BK 117	Rotor Flight Controls - Main Rotor Controls Power Boosted Section - Inspection / Rigging
2010-0245	2010-11-26	AIRBUS	A340	Fuselage - Fuselage Internal Structure at Frame 39.1 - Inspection
2010-0233	2010-11-26	DYN AVIATION	CAP 10	Flight Controls - Turnbuckles - Inspection
US-2010-25-51	2010-11-26	BELL	212	NOT ADOPTED - SEE EASA EMERGENCY AD 2010-0246-E
US-2010-18-13	2010-11-26	PRATT & WHITNEY	PW4000, PW4070, PW4080, PW4090, PW4100	Engines - High-Pressure Compressor (HPC) Drum Rotor Disk Assembly - Inspection / Replacement
2010-0249	2010-11-26	BAE SYSTEMS (OPERATIONS) LTD	ATP, HS748	Flight Controls - Control Column Lower Aileron Chain Drives - Modification
2010-0246-E	2010-11-26	AGUSTA, BELL	AB 212, 212	Rotors - Main Rotor Hub Inboard Strap Fitting - Identification / Replacement
2010-0247-E	2010-11-26	EUROCOPTER DEUTSCHLAND	BK 117, EC 135, EC 635	Lights - Instrument Lighting Display Brightness for Flight in Night Vision Goggle (NVG) Mode - Reduction
2007-0070R1	2010-11-25	AIRBUS	A330	Landing gear - Nose Wheel Steering System - Rotating Sleeve - Inspection / Modification
US-2010-24-03	2010-11-25	ROBINSON	R22	Tail Rotor (T/R) - Control Pedal Bearing Block Support - Inspection / Replacement
2010-0172-CN	2010-11-25	MD HELICOPTER	MD900	CANCELLATION NOTICE - Main Rotor - Main Rotor (MR) Lower Hub Assembly - Inspection
2010-0029R1	2010-11-25	DASSAULT	FALCON 7X	Electrical Power & Hydraulic Power - Electrical Wirings & Hydraulic Lines Routing - Modification(s)
2007-0069R1	2010-11-25	AIRBUS	A340	Landing gear - Nose Wheel Steering System - Rotating Sleeve - Inspection / Modification
US-2010-18-52	2010-11-25	MD HELICOPTER	MD900	Main Rotor - Main Rotor (MR) Lower Hub Assembly - Inspection
US-2010-10-17	2010-11-24	MITSUBISHI	MU2B	[Correction] Engine Torque Indication System Inspections - AFM Update (latest revision)
2010-0239-E	2010-11-23	AIRBUS	A300-600, A300- 600ST BELUGA	[Correction] Flight Control - Elevator Mechanical Control Linkage - Pitch Uncoupling Unit - Inspection
US-2010-24-52	2010-11-23	BELL	212	SUPERSEDED BY FAA EMERGENCY AD 2010-25-51
2010-0243-E	2010-11-23	AGUSTA	AB 212	SUPERSEDED BY EASA AD 2010-0246-E
US-2010-23-15	2010-11-23	BOEING	777	Wings - Sealant - Removal / Repair
2010-0242-E	2010-11-22	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - High Pressure / Intermediate Pressure (HP/IP) Structure - Inspections



Publ. number	Issue Date	TC Holder	Type	Subject
2010-0237R1	2010-11-22	AGUSTA, EUROCOPTER DEUTSCHLAND, Eurocopter UK Ltd, KEYSTONE HELICOPTER, SIKORSKY	AB 139, AW 139, BK 117, EC 135, CAA UK AAN 26529, STC EASA.10028851 , STC EASA.R.S.01532, STC EASA.IM.R.S.0125 6, STC SR02408NY-D, S92	Equipment / Furnishings - Spectrolab Nightsun XP Searchlight - Inspection / Removal / Replacement
2010-0241	2010-11-22	SIKORSKY	S92	Main Rotor Drive - Main Gearbox (MGB) - Inspection / Replacement
2010-0240-E	2010-11-19	AGUSTA	AB 212	SUPERSEDED BY EASA AD 2010-0243-E
2010-0238-E	2010-11-18	EUROCOPTER	EC225	Main Rotor - Repaired Blade - Inspection / Replacement / Repair
US-2008-26-10	2010-11-17	CESSNA	172, 172RG, 175, 177, 177RG, 180, 182, 185, 206, 207, 208, 210, 336, 337, A185, F172, F177RG, F182, F337, FR172, FR182, FT337, M337, P172	[Correction] Alternate static air source selector valve - Inspection / Replacement
US-2010-24-51	2010-11-16	BELL	212	SUPERSEDED BY FAA EMERGENCY AD 2010-24-52
US-2010-23-13	2010-11-15	BOEING	757	Wings - Lower Fixed Leading Edge Panel Assemblies - Modification