



Publ. number	Issue Date	TC Holder	Type	Subject
2011-0067-E	2011-04-15	BRP-POWERTRAIN GMBH	912 A, 912 F, 912 S, 914 F	Ignition - Magneto Flywheel Hub Washer - Replacement
US-2011-08-01	2011-04-15	BELL	212	Rotor - Fitting - Inspection / Replacement
DLP-0828-11	2011-04-13	ANTONOV ASTC	An-24, An-26, An-30, An-32	Fuel Pump Junction Box, RH Main Junction Box and LH Main Junction Box Fuses - One-time Inspection / Adjustment
US-2011-08-06	2011-04-13	HONEYWELL INTERNATIONAL INC	LTP101, LTS101	Power Turbine Rotors - Identification / Replacement
CF-2011-05	2011-04-12	BOMBARDIER	BD100 1A10	Horizontal Stabilizer Trim Actuator - Airworthiness Limitation Tasks
2011-0066	2011-04-11	TURBOMECA	TM 333	Engine - Maintenance Manual - Airworthiness Limitation Section Update
2011-0065	2011-04-07	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Fire Protection - Baggage Bay Fire Bottles Wiring Looms - Inspection / Modification
2011-0064	2011-04-07	FOKKER SERVICES	F27	Fuselage - Rear Fuselage Lap Joint - Inspection / Repair
BR-2009-10-01R3	2011-04-07	EMBRAER	EMB500	Airplane Flight Manual - Section 4 Abnormal Procedures - Revision
2011-0063-E	2011-04-06	TECNAM	P2006T	Landing Gear- Emergency Accumulator for Landing Gear Extension - Inspection / Replacement
US-2011-08-51	2011-04-06	BOEING	737	Fuselage Lap Joint at Stringers S-4R and S-4L - Inspection / Repair
US-2011-07-04	2011-04-05	BOEING	DC-9	Fuel - In-Line Fuses - Wiring Spars - Installation
US-2011-06-10	2011-04-05	PIPER	PA46	Engine Indicating - Turbine Inlet Temperature (T.I.T.) Indicators/Probes - Inspection / Replacement
US-2011-07-13	2011-04-05	COMMANDER (CPAC, INC.)	112, 114	Elevator Spar Inspection / Repair / Replacement
2011-0062	2011-04-04	AIRBUS	A330	Engine - Engine Air Intake Cowl Assembly - Piccolo Tube - Inspection