



Publ. number	Issue Date	TC Holder	Type	Subject
2011-0088	2011-05-13	AIRBUS	A340	Doors - Nose Landing Gear (NLG) Aft Doors - Hinge Attachment Fittings and Swan Neck - Inspection/Replacement
2011-0083	2011-05-12	FOKKER SERVICES	F27, F28	Electrical Power - Electrical Power Center (EPC) and Battery Relay Panel - Inspection / Adjustment
2011-0085	2011-05-12	AIRBUS	A300-600, A310	Doors - Forward Cargo Door High Pressure Pipe - Replacement
2011-0086	2011-05-12	AIRBUS	A300, A300-600, A310	Fuselage - Cross Beam at Junction with Lower Cargo Door Actuator Beam - Inspection / Modification
BR-2011-05-03	2011-05-12	EMBRAER	EMB500	Flight Controls - Angle of Attack (AOA) Sensors, Cover Plates and Sealants - Rework / Replacement
US-2011-06-02	2011-05-12	CESSNA, THIELERT AIRCRAFT ENGINES	172, F172, STC 10014287, STC SA01303WI	NOT ADOPTED - EASA DECISION ATTACHED
2011-0087-E	2011-05-12	THIELERT AIRCRAFT ENGINES	TAE125	Engine - Friction Disk - Replacement
2011-0082	2011-05-10	BRP-POWERTRAIN GMBH	914 F	Engine Fuel & Control - Fuel Pressure Regulator - Identification / Replacement
BR-2006-11-01R6	2011-05-09	EMBRAER	ERJ190	[Corrected] Hamilton Sundstrand Low Pressure Check Valve (LPCV) - Periodic Replacement
2011-0081	2011-05-09	AGUSTA	AB 139, AW 139	Tail Rotor - Tail Rotor Blades - Inspection
BR-2011-05-02	2011-05-09	EMBRAER	ERJ190	Air Management System (AMS) Controller Processor Modules - Replacement
BR-2011-05-01	2011-05-09	EMBRAER	ERJ170	Air Management System (AMS) Controller Processor Modules - Replacement
2011-0080	2011-05-06	ROLLS-ROYCE PLC	RB211 TRENT 800	Engine - Front Combustion Liner Head Section - Inspection/Replacement
2009-0187R2	2011-05-06	ROLLS-ROYCE PLC	RB211 TRENT 700, RB211-524, RB211-535	Engine - Front Combustion Liner Head Section - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2011-0077	2011-05-05	AIRBUS	A319, A320, A321	Equipment / Furnishings -Cargo Loading System Fixed YZ Latches Attachment Points - Modification
2011-0058R1	2011-05-05	AIRBUS	A380	Pneumatic - Pylon Bleed Duct - Inspection / Replacement
2011-0079	2011-05-05	SAAB AB, AERONAUTICS	2000	Electrical and Electronics Installation - Electrical Connectors and Braids - Inspection / Repair / Replacement
2011-0078	2011-05-05	SAAB AB, AERONAUTICS	340	Flight Controls - Elevator Pushrod Assembly - Identification / Inspection / Replacement
US-2011-04-02	2011-05-05	HAMILTON SUNDSTRAND	247F	[Correction] Propellers - Propeller Blades - Removal
CF-2011-08	2011-05-05	BOMBARDIER	CL-600 (Challenger)	Air-Driven Generator Electrical Power Feeder Cable - Potential Failure Due To Corrosion
US-2011-09-14	2011-05-04	BOEING	747	Engine Strut Mid-Pivot Access Door and Bolt Assembly - Inspection / Replacement
US-2011-09-02	2011-05-03	HONEYWELL INTERNATIONAL INC, SAAB AB, AERONAUTICS, STANDARD AERO	STC ST00146WI-D, STC ST00224WI-D, 340, STC SA984GL-D	Fuselage - Antenna External Adapter Plate Area - Inspection / Repair
US-2011-09-11	2011-05-03	BOEING	777	Nacelles/Pylons - Disconnect Box - Inspection / Replacement
US-2011-09-15	2011-05-03	BOEING	777	Fuel - Ground Fault Interrupter (GFI) Relays - Electrical Load Management System (ELMS) Software/Wiring/Bonding - Installation / Replacement
BR-2005-09-03R3	2011-05-03	EMBRAER	ERJ170	Pneumatic - Low Pressure Check Valves (LPCV) - Replacement
CF-2011-07	2011-05-03	BOMBARDIER	CL-600 (Regional Jet)	Roll Control System - Aileron Stiffness