



Publ. number	Issue Date	TC Holder	Type	Subject
US-2012-03-12	2012-03-02	GENERAL ELECTRIC	CF6-80C	Engine - No. 3 Bearing Packing - Inspection / Replacement
US-2012-04-04	2012-03-02	PRATT & WHITNEY	PW4000	Engine Fuel & Control - Fuel Metering Unit - Replacement
US-2012-03-52	2012-03-01	MOONEY AVIATION COMPANY INC.	M20	[Final Rule] Tail Pitch Trim Assembly - Inspection
US-2012-02-17	2012-03-01	BOEING	757	Wings - Front Spar Lower Chord - Inspection / Repair
US-2012-02-15	2012-03-01	BOEING	757	Electrical Power - Power Feeder Wire Bundles Support Clamps - Inspection / Repair
2011-0020R1	2012-02-29	DIAMOND AIRCRAFT INDUSTRIES	DA42, DA42M	Landing Gear - Main Landing Gear Damper-to-Trailing Arm Joints - Inspection / Replacement
2012-0034	2012-02-29	AIRBUS	A330, A340	Landing Gear - Nose Landing Gear (NLG) Retraction Actuator-Overhaul
2011-0058R3	2012-02-29	AIRBUS	A380	Pneumatic - Pylon Bleed Duct - Inspection / Replacement
2010-0023R2	2012-02-28	EUROCOPTER	AS 355	Fuselage - Engine and Main Gearbox Cowling Locking - Modification
2012-0033R1	2012-02-27	EUROCOPTER	AS 350	Fire Protection - Fire Detection System - Modification
2012-0032	2012-02-24	AIRBUS	A318, A319, A320, A321	Wings - Outer Wing Main Landing Gear Support Rib 5 Fitting - Inspection / Modification
DCA-R2000-40	2012-02-23	ALPHA AVIATION CONCEPT LTD	HR 200, R 2000	Engine Oil System - Oil Lines - Replacement
US-2012-03-02	2012-02-23	BOEING	767	Air Conditioning - Cabin Air Conditioning and Temperature Control System (CACTCS) - Relay and Wiring Bundle - Installation / Replacement
2012-0031	2012-02-22	AIRBUS	A340	Doors - Center Landing Gear Main Doors Forward Fittings - Inspection / Replacement
BR-2012-02-01	2012-02-22	EMBRAER	ERJ170	Wings - Spar II - Inspection / Repair
US-2012-03-07	2012-02-22	LYCOMING	AEIO-320, AEIO-360, AEIO-540, AIO-320, AIO-360, GO-435, GO-480, HIO-360, HO-360, IGO-480, IGO-540, IGSO-480, IGSO-540, IO-320, IO-360, IO-540, IO-720, IVO-360, IVO-540, LIO-320, LIO-360, LO-360, LTIO-540, LTO-360, O-235, O-290, O-320, O-340, O-360, O-435, O-540, TIGO-541, TIO-360, TIO-540, TIO-541, TIVO-540, TO-360, TVO-435, TVO-540, VO-360, VO-435, VO-540	Engines - Carburetor - Inspection / Replacement
US-2012-02-14	2012-02-21	BOEING	737	Engine Exhaust - Thrust Reverser Torque Boxes - Aero/fire Seals - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2012-09	2012-02-21	BOMBARDIER	DHC-8	Loss of the 400Hz Fixed Frequency System Due To Multiple Inverter Failures