



Publ. number	Issue Date	TC Holder	Type	Subject
2012-0093-E	2012-05-26	BRP-POWERTRAIN GMBH	912 A, 912 F, 912 S	Engine - Fuel and Control - Fuel Pump - Replacement
CF-2012-17	2012-05-25	BOMBARDIER	DHC-8	Aft Entry & Aft Service Doors - Translating Door Handle Jamming
2012-0092	2012-05-25	AIRBUS	A300-600	Wings - Center Wing Box Frame 47 Angle Fittings - Inspection / Modification
2012-0091	2012-05-25	AIRBUS	A300-600, A300-600ST BELUGA, A310	Fuel / Main Transfer System - Inner, Centre and Trim Tank Fuel Pump Control Circuit - Modification
CF-2011-29R1	2012-05-25	BOMBARDIER	DHC-8	Hydraulic Accumulators - Screw Cap/End Cap Failure
2012-0089	2012-05-24	AIRBUS	A380	Wings - Die-Forged Front Spar - Inspection / Repair
US-2012-10-13	2012-05-24	CONTINENTAL MOTORS, INC	IO-550, TSIO-520, TSIO-550, TSIOF-550	Engines - Starter Adapters - Replacement
2011-0233-CN	2012-05-24	FOKKER SERVICES	F28	CANCELLATION NOTICE - Fuel - Wing and Integral Center Wing Tanks - Inspection / Modification [Fuel Tank Safety]
US-2012-09-09	2012-05-24	INTERNATIONAL AERO ENGINES	V2500-()5, V2500-A1	Engine - High-Pressure Compressor (HPC) Stage 3 to 8 drums - Inspections / Replacement
2010-0046R1	2012-05-23	AIRBUS	A318, A319, A320, A321	Flight Controls - Elevator Servo-Control Rod Eye-end - Inspection
US-2012-10-03	2012-05-23	BOEING	747	Fuselage - Skin Lap Splice - Inspections / Repair
US-2012-09-14	2012-05-23	BOEING	777	Doors - Retention Bolts - Inspections / Replacement
2010-0245R1	2012-05-22	AIRBUS	A340	Fuselage - Fuselage Internal Structure at Frame 39.1 - Inspection
2009-0208R2	2012-05-22	DASSAULT	FALCON 7X	Navigation - Radio-altimeter Lock-up - Operational Procedure
2012-0090	2012-05-22	AIRBUS	A330, A340	Air Conditioning - Bulk Cargo Isolation Valve Bonding Lead and Route 1M - Modification
US-2012-10-02	2012-05-22	HAWKER BEECHCRAFT CORPORATION	58, G58	Fuel - Fuel Hose Clamps - Inspection / Replacement
CF-2012-14R1	2012-05-22	BELL, DART AEROSPACE LTD	412, STC EASA.IM.R.S.01304, STC SH01-9, STC SR01298NY	High Gear Aft Crosstubes - Life Limitation
2012-0086-E	2012-05-18	AGUSTAWESTLAND	AB 412, AB 412EP	Equipment & Furnishings - Hoist Hook - Inspection
2012-0087-E	2012-05-18	EUROCOPTER	EC225	Main Rotor Drive - Main Gear Box Bevel Gear Vertical Shaft - Inspection / Limitation



Publ. number	Issue Date	TC Holder	Type	Subject
US-2012-10-52	2012-05-18	CONTINENTAL MOTORS, INC	TSIO-520	Hartzell Engine Technologies, LLC (HET) Turbochargers - Removal
2012-0085-E	2012-05-17	EUROCOPTER DEUTSCHLAND	EC 135, EC 635	Main Rotor System - Main Rotor Hub - Inspection / Replacement
2012-0083	2012-05-16	AIRBUS	A318, A319, A320, A321	Oxygen - Chemical Emergency Oxygen Containers - Identification / Modification
2012-0084	2012-05-16	EUROCOPTER	AS 332, AS 365, EC 155, EC225, SA 365	Equipment and Furnishings - EADS SOGERMA Flight Crew Seats - Inspection / Replacement
2012-0082	2012-05-15	AIRBUS	A330, A340	Flight Controls - Wing Tip Brakes - Operational Test/Replacement
US-2012-09-04	2012-05-15	BOEING	767	Fuselage - Fail-Safe Straps - Inspection / Repair / Replacement
US-2012-09-08	2012-05-15	BOEING	767	Fuselage - Aft Pressure Bulkhead at Station (STA) 1582 - Inspections / Repair / Replacement
2012-0081	2012-05-14	DASSAULT	FALCON2000EX	Airplane Flight Manual - Take-Off Under Out-Of- Trim Condition - Operational Limitation
CF-2005-41R1	2012-05-14	BOMBARDIER	CL-600 (Regional Jet)	Shear Pin Failure In The Pitch Feel Simulator Unit