



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-----------------------------|-----------------------------------|--|
| US-2012-08-01 | 2012-06-08 | SIKORSKY | S-92 | Rotorcraft Flight Manual - Revision |
| 2012-0102 | 2012-06-08 | AIRBUS | A300-600, A300-600ST BELUGA, A310 | Equipment and Furnishings - Powered Pilot and Co-pilot Seats - Inspection |
| 2012-0099 | 2012-06-08 | PILATUS AIRCRAFT LTD | PC-12 | Time Limits / Maintenance Checks - Airworthiness Limitation Section - Amendment / Implementation |
| 2012-0100 | 2012-06-06 | AIRBUS | A318, A319, A320, A321 | Nacelles/Pylons - Aft Pylon Moveable Fairing Rib 5 - Inspection / Repair |
| US-2012-08-08 | 2012-06-06 | LEARJET | 45 | NOT ADOPTED - SEE EASA PROPOSED AD (PAD) 12-062 |
| US-2012-11-03 | 2012-06-04 | BOEING | 777 | Wings - Main Landing Gear (MLG) - Fuse Pins - Inspection / Replacement |
| 2012-0096 | 2012-06-04 | AIRBUS | A380 | Airborne Auxiliary Power - Suspension System Assembly - Replacement |
| 2012-0098-E | 2012-06-04 | EUROCOPTER | AS 365, EC 155, SA 365 | Rotorcraft Flight Manual - Emergency Procedures - Rush Revision |
| 2012-0092 | 2012-06-04 | AIRBUS | A300-600 | [Correction] Wings - Center Wing Box Frame 47 Angle Fittings - Inspection / Modification |
| 2012-0097R1 | 2012-06-01 | BRP-POWERTRAIN GMBH | 912 A, 912 F, 912 S | Engine Fuel and Control - Fuel Pump Pressure Side Hose - Replacement |
| US-2012-11-07 | 2012-06-01 | HONEYWELL INTERNATIONAL INC | ALF502, LF507 | Engines - Overspeed Trip System - Checks |
| CF-2012-18 | 2012-06-01 | BOMBARDIER | CL-600 (Regional Jet) | Defective Horizontal Stabilizer Trim Actuators |
| 2012-0094 | 2012-05-31 | AIRBUS | A330 | Engine - Forward Engine Mounts Bolts - Torque Check/ Replacement |
| 2012-0095-CN | 2012-05-31 | PIAGGIO | P180 | CANCELLATION NOTICE - Brakes - Copilot / Pilot Brake Rods - Inspection |
| US-2012-11-06 | 2012-05-30 | GULFSTREAM | G1159, G1159A, G1159B | Wings and Fuselage - Inspection / Repair |
| US-2012-10-04 | 2012-05-29 | CESSNA | 210, P210, T210 | Wings - Left and Right Wing Lower Main Spar Caps - Inspection / Repair |
| US-2012-10-10 | 2012-05-29 | BOEING | 777 | Stabilizers - Horizontal Stabilizer Pivot Pins - Replacement / Inspection |
| US-2012-10-09 | 2012-05-29 | PIPER | PA31T | Placards and Markings |