



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|---|--|---|
| US-2013-08-12 | 2013-04-26 | BOEING | 787 | Main and APU Battery Enclosures and ECS Ducts - Installation; Main and APU Batteries and Battery Chargers - Replacement; and Aircraft Maintenance Program - Amendment |
| 2013-0099 | 2013-04-25 | AIRBUS | A340 | Nacelles / Pylons - Lower Center and Aft Pylon Spigots - Inspection / Replacement |
| US-2013-08-23 | 2013-04-25 | BOEING | DC-10, MD-10, MD-11 | Fuel - Fuel System-Review |
| 2013-0097 | 2013-04-24 | AIRCRAFT INDUSTRIES | L-410, L420 | Aircraft Flight Manual - Procedure Manually Switching Off Water Injection System - Introduction |
| 2013-0098-E | 2013-04-24 | EUROCOPTER | EC225 | Engine Controls - Emergency Shutdown / Fuel Shut-Off and General Cut-Out Control Tangential Gearboxes - Check / Lubrication / Replacement |
| CF-2013-10 | 2013-04-24 | BOMBARDIER | CL-600 (Regional Jet) | Flight Data and Cockpit Voice Recorder Paint/Marking Deterioration |
| US-2013-08-09 | 2013-04-22 | BOEING | 777 | Oxygen - Clamshell Couplers - Inspection / Installation |
| US-2013-08-02 | 2013-04-22 | BOEING | 777 | Stabilizers - Elevator Actuator Fittings - Inspection / Replacement |
| US-2013-06-51 | 2013-04-18 | AGUSTAWESTLAND, BELL, MD HELICOPTERS INC (MDHI), SIKORSKY | AB 412, AB 412EP, 212, 214, 412, STC SH3189SO, MD900, S-61, S-76, S-92 | PARTIALLY ADOPTED [SEE EASA AD 2013-0077R1] Equipment / Furnishing - Hoist - Inspection / Replacement |
| CF-2013-11 | 2013-04-18 | BOMBARDIER | CL-215 | Cracking of the Wing Lower Spar and Wing Lower Skin |
| 2013-0096 | 2013-04-18 | ROLLS-ROYCE PLC | TRENT 1000 | Engine - Intermediate Pressure Turbine Blades - Inspection |
| US-2013-07-09 | 2013-04-18 | BOEING | 737, 747, 767 | Oxygen - Oxygen Mask Stowage Box Unit - Inspection / Replacement |
| 2013-0093 | 2013-04-17 | EUROCOPTER | EC 120, EC 130 | [Correction] Doors - Sliding Door Star Support - Modification |
| 2006-0265-CN | 2013-04-17 | VARIOUS | | CANCELLED: Navigation Systems - Mode C and S Transponders - Check |
| US-2013-07-07 | 2013-04-17 | BOEING | 737 | Stabilizers - Horizontal Stabilizers Rear Spar Attach Pin Part Number - Inspection / Replacement |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-----------------------------|---|---|
| US-2013-05-16 | 2013-04-17 | MD HELICOPTERS INC (MDHI) | 369 | Rotorcraft Tailboom - Inspection / Modification / Installation |
| 2012-0270R1 | 2013-04-16 | BRITTEN-NORMAN AIRCRAFT LTD | BN2A (Islander), BN2A Mark III (Trislander) | Fuel System - Tank Filler Cap and Receptacle - Inspection / Replacement |
| US-2013-07-10 | 2013-04-16 | INTERNATIONAL AERO ENGINES | V2500-()5 | Engines - No. 4 Bearing Internal Scavenge Tube - Replacement / Installation |
| US-2013-07-11 | 2013-04-16 | BOEING | 777 | Fuselage - Scribe Lines - Inspection / Repair |
| US-2013-05-17 | 2013-04-16 | SIKORSKY | S-61 | Fuel - Forward and Aft Fuel System 40 micron Fuel Filter Element - Replacement |
| 2013-0095-E | 2013-04-16 | EUROCOPTER | AS 350, AS 355 | Rotor Flight Controls - Main/Tail Rotor Servo-Control Bearings - Inspection / Replacement |
| 2013-0094 | 2013-04-16 | AIRBUS | A330 | Power Plant - Upper Aft Mount Bolts - Inspection / Repair |
| US-2013-06-05 | 2013-04-16 | BOEING | 737 | Flight Controls - Elevator Tab Control Mechanism - Inspection / Replacement |
| US-2013-07-08 | 2013-04-15 | BOEING | 757 | Wings - Wing Center Section Secondary Fuel Barrier - Inspection / Repair |
| US-2013-05-02 | 2013-04-15 | BOEING | DC-9, MD-88 | Stabilizers - Horizontal Stabilizer Ribs - Inspection / Repair / Replacement |
| 2013-0092 | 2013-04-15 | AIRBUS | A330, A340 | Wings - Inner Rear Spar Upper Build Slot - Inspection / Modification |