



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2014-18	2014-06-20	BOMBARDIER	DHC-8	Main Landing Gear - Improperly Stowed Parking Brake Hand Pump Lever in Right Hand Side Nacelle
2014-0151	2014-06-20	FOKKER SERVICES	F27	Time Limits / Maintenance Checks - Maintenance Requirements - Implementation
2014-0152	2014-06-20	ROLLS-ROYCE PLC	RB211 TRENT 500, RB211 TRENT 700, RB211 TRENT 800, RB211 TRENT 900	Engine - Intermediate Pressure Compressor Rotor Shaft and Balance Weights - Inspection / Modification
2012-0170R2	2014-06-20	AIRBUS HELICOPTERS	AS 365, EC 155, SA 365, SA 366	Time Limits and Maintenance Checks - Tail Rotor Gearbox (TGB) Oil Level and Magnetic Chip Detector - Inspection Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement
2014-0150	2014-06-18	AGUSTAWESTLAND	A109, AW109SP	Stabilizers - Vertical Fin Vibration Absorber - Inspection / Removal
DCA-750XL-16A	2014-06-18	PACIFIC AEROSPACE LTD	750XL	Fin Forward Pickup - Inspection
CF-2014-17	2014-06-18	BOMBARDIER	CL-600 (Challenger)	Additional limitation for landing/taxi light operations on ground due to potential fuel leakage
CF-2014-16	2014-06-18	BOMBARDIER	CL-600 (Regional Jet)	Landing Gear - Alternate Extension System (AES) - Incorporation of New Certification Maintenance Requirement
BR-2014-06-01	2014-06-16	EMBRAER	EMB-135, EMB-145	Navigation - Pitot #1 and Pitot #2 Tube Assembly Lines / Inspection - Tube Ribbon Heater -Installation / Replacement Airplane Flight Manual (AFM) - Revision
2014-0136	2014-06-13	AIRBUS	A330, A340	Fuselage - Frame (FR) 40 / Fuselage Skin Panel Junction - Inspection
2014-0149	2014-06-13	AIRBUS	A330, A340	Wings - Center Wing Box Fastener Holes at Frame 40 Vertical Web - Inspection
2014-0148	2014-06-13	AIRBUS	A330, A340	Fire Protection / Lights / Pneumatic / Fuselage - Prevention against Explosion Risks in Section 19 - Modifications
2014-0145R1	2014-06-13	AIRBUS HELICOPTERS	EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
CF-2014-15	2014-06-12	BOMBARDIER	DHC-8	Hydraulic Power - Main Landing Gear Alternate Extension System Reservoir - Leakage due to Incorrect Lid Assembly
US-2014-12-52	2014-06-11	HONEYWELL INTERNATIONAL INC	TFE731, TFE731-20/-40/-50/-60	Engine - Second Stage Low Pressure Turbine Blades - Identification / Removal from Service



Publ. number	Issue Date	TC Holder	Type	Subject
2014-0142R1	2014-06-11	ZODIAC AEROTECHNICS	Oxygen masks	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement
2014-0146	2014-06-11	AIRBUS	A319, A320, A321	Fuselage - Frame 24 at Stringer 17/18 - Inspection
2014-0144R1	2014-06-11	ATR	ATR42, ATR72	[Correction] Fire protection - Engine Fire Extinguishing Pipe - Inspection
2014-0147	2014-06-11	AIRBUS	A318, A319, A320, A321	Flights Controls - Trimmable Horizontal Stabilizer Actuator - Inspection