



Publ. number	Issue Date	TC Holder	Type	Subject
2014-0183-E	2014-08-01	LANGE FLUGZEUGBAU GmbH	E1 Antares	Hydraulic Power - Hydraulic Pump Shaft Coupling - Replacement
2014-0182-E	2014-08-01	LANGE FLUGZEUGBAU GmbH	E1 Antares	Electric Power - Capacitor Board - Modification
2014-0181	2014-07-31	PILATUS AIRCRAFT LTD	PC-6	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment / Implementation
2014-0180	2014-07-30	AIRBUS HELICOPTERS DEUTSCHLAND	BK 117, BO 105	[Correction] Main Rotor - Swashplate Assembly - Inspection / Replacement
2014-0179R1	2014-07-29	AIRBUS HELICOPTERS	AS 365, EC 155, SA 365, SA366G1	Rotor Drive(s) - Tail Rotor Drive Flange - Inspection
BR-2014-07-03	2014-07-28	EMBRAER	EMB-500 (Phenom 100)	Horizontal Stabilizer- to- Vertical Stabilizer Attachment Joint Barrel Nuts - Inspection / Replacement
BR-2014-07-02	2014-07-25	EMBRAER	EMB-500 (Phenom 100)	SUPERSEDED BY BRAZILIAN EMERGENCY AD 2014-07-03
2013-0284R1	2014-07-25	AIRBUS HELICOPTERS	AS 350	Rotor Drive - Hydraulic Pump - Inspection / Replacement
2014-0178	2014-07-25	AIRBUS	A318, A319, A320, A321	Fuselage - Passenger Door Girt Bar Fittings - Inspection
2012-0267R2	2014-07-25	AIRBUS	A380	Passenger Oxygen - Oxygen Distribution Pressure Line and Container Manifolds - Inspection
2014-0175	2014-07-25	AGUSTAWESTLAND	A119, AW119	Powerplant - Engine Reduction Gear Box Bearings - Inspection / Replacement
2014-0177	2014-07-25	AIRBUS	A319, A320, A321	Fuselage - Rear Fuselage Clips, Shear Webs and Angles - Replacement
2014-0176	2014-07-25	AIRBUS	A319, A320	Fuselage - Longerons below Emergency Exit Cut-outs - Modification
US-2014-13-07	2014-07-24	BOEING	737	Lights - Tail Strobe Light Housing - Installation
2014-0174	2014-07-23	AIRBUS	A318, A319, A320, A321	Navigation - Terrain Awareness Warning System - Power Cycle (Reset)
CF-2014-23	2014-07-22	BOMBARDIER	BD-700	Flight Controls - Restricted Movement of the Aileron Pulley and Control Cables
2014-0169	2014-07-22	AIRBUS	A320	[Correction] Wings - Inner Rear Spar - Modification
CF-2014-20	2014-07-22	BOMBARDIER	CL-600 (Regional Jet)	Power Plant - Engine Fan Cowl Panel Dislodgement During Flight
CF-2014-22	2014-07-22	BOMBARDIER	DHC-8	Flight Controls - Outboard Spoiler Power Control Unit (PCU) - Inadvertent Spoiler Deployment
2014-0173	2014-07-22	AIRBUS	A340	Exhaust - Thrust Reverser "J-Ring" at 6 and 12 o'clock Beam - Inspection / Replacement
US-2014-12-13	2014-07-21	BOEING	737	Wings - Aft Support Fitting, Rear Spar Upper Chord, and Rear Spar Web - Inspection