



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0037	2016-02-26	PILATUS AIRCRAFT LTD	PC-12	Wings - Wing-To-Fuselage Attachment Torlon Plates - Inspection
DCA-750XL-7B	2016-02-25	PACIFIC AEROSPACE LTD	750XL	Wings - Maximum Certified Takeoff Weight Limitation and Wing - Modification
US-2016-04-08	2016-02-24	BOEING	787	Wings - Maintenance or Inspection Program - Revision
2016-0034	2016-02-24	ROLLS-ROYCE DEUTSCHLAND	BR700-710	Engine - Low Pressure Turbine Fuel Shut-Off Pawl Carrier Pivot Pin - Replacement
2016-0033	2016-02-24	GUIMBAL, HELICOPTERES	CABRI	Powerplant - Engine Cooling Fan - Replacement / Inspection
2016-0032	2016-02-24	GUIMBAL, HELICOPTERES	CABRI	Time Limits / Maintenance Checks - Airworthiness Limitation Section - Amendment / Implementation
2016-0035	2016-02-24	AIRBUS	A340	Fuselage - Structure Frames and Joints - Modification / Reinforcement
2016-0029	2016-02-23	FOKKER SERVICES	F28	Fuselage - Upper Fuselage Skin External Doublers at TCAS Antenna Position - Inspection
US-2016-04-07	2016-02-23	BOEING	767	Fuselage - Skin / Upper and Lower Splice Fittings - Inspection / Repair
2016-0030	2016-02-23	FOKKER SERVICES	F27	Nacelles / Pylons - Engine Nacelle Stringers - Inspection
2016-0031	2016-02-23	ROLLS-ROYCE PLC	RB211-535	Engine / Critical parts - Engine Health Check and Revised Operating Procedures / Critical Part Identification and Replacement
US-2016-04-02	2016-02-19	BOEING	747	Fuselage - Fuselage Skin Lap Joints - Repetitive Inspections / Modification
US-2016-04-03	2016-02-19	BOEING	747	Fuselage - Nose Cargo Door Portal - Inspections / Corrective Actions
US-2016-03-01	2016-02-17	BOEING	737	Wings - Front Spar Lower Chord, Inspar Skin and Wing Skin - Repetitive Inspections / Corrective Actions
2016-0010R1	2016-02-16	AIRBUS	A318, A319, A320, A321	Powerplant - Aft Engine Mount Retainers - Inspection / Replacement
2013-0133-CN	2016-02-16	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	CANCELLED: Tail Rotor - Tail Rotor Hub Pitch Horn - Inspection / Replacement
CF-2016-01R1	2016-02-15	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Tail Rotor - Pitch Link Corrosion
CF-2016-03R1	2016-02-15	BOMBARDIER	CL-600 (Regional Jet)	Flight Controls - Flap and Slat Torque Tube Corrosion
2016-0028	2016-02-15	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Equipment / Furnishing - Internal Life Rafts - Inspection