



Publ. number	Issue Date	TC Holder	Type	Subject
2004-0009R3	2016-03-23	ROLLS-ROYCE CORPORATION (USA)	250 Series II, 250-C28/-C30/-C47	Engine Fuel & Control - Engine Fuel System Pipes - Inspection
2016-0062	2016-03-23	SPEKON SÄchsische Spezialkonfektionen GmbH	RE-5L	Equipment / Furnishings - Emergency Parachute Harness - Modification
US-2016-04-17	2016-03-23	BOEING	777	Fuselage - Fuselage Skin Lap Splices - Inspection / Modification
2016-0061	2016-03-23	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - High Pressure / Intermediate Pressure Structure Oil Service Tube Buffer Sealing Rings - Removal and Inspection
US-2016-05-07	2016-03-23	ENGINE ALLIANCE LLC	GP7200	Engine - High-Pressure Compressor (HPC) Rotor Stage 2 to 5 and Stage 7 to 9 Spools - Removal and Replacement
2016-0060	2016-03-23	AIRBUS HELICOPTERS DEUTSCHLAND	BO 105, MBB-BK 117	Main Rotor - Swashplate Assembly - Replacement / Inspection
2016-0059-E	2016-03-22	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Tail Rotor - Metal Blades / Skin - Inspection
CF-2016-09	2016-03-22	BELL HELICOPTER TEXTRON CANADA (BHTC)	206	Main Rotor - Corrosion of Tension-Torsion Straps
2016-0058	2016-03-21	AIRBUS	A300, A300-600, A300-600ST (Beluga)	Landing Gear - Main Landing Gear Hinge Arm / Barrel Pin - Inspections
US-2016-05-12	2016-03-21	BOEING	747	Fuselage - Tension Ties, Shear Webs, and Frames of the Upper Deck - Inspection / Modification / Repair
US-2016-06-05	2016-03-21	BOEING	777	Nacelles / Pylons - Engine Aft Pylon Area - Repair
US-2016-06-07	2016-03-21	BOEING	747	Fuselage - Nose Wheel Well (NWW) - Inspection / Replacement / Repair
US-2016-06-02	2016-03-18	BOEING	737	Stabilizers - Horizontal Stabilizer - Inspection
US-2016-06-08	2016-03-18	BOEING	787	AFM Change - Fan Ice Removal Procedure / Engine - Fan Stator Module Assembly - Rework



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2016-03-01	2016-03-18	EMBRAER	EMB-135, EMB-145	Navigation - Pitot #1 and Pitot #2 Tube Assembly Lines - Installation / Replacement / Airplane Flight Manual (AFM) Revision
2016-0056	2016-03-18	AIRBUS	A318, A319, A320, A321	Flight Controls - Spoiler Elevator Computer Software update
2016-0057	2016-03-18	AIRBUS	A300-600	Fuselage - Skin Lap Joint - Inspection / Repair
US-2016-04-21	2016-03-18	BOEING	DC-8	Wings - Lower Wing Skins, Stringers, and Splice Fitting Fastener Holes - Inspection
2016-0055	2016-03-17	TURBOMECA	ARRIEL 2	Engine - Accessory Gear Box Module M01 - Inspection / Replacement
US-2016-03-06	2016-03-17	BOEING	DC-9, MD-88, MD-90	Fuel - Fuel Pump - Installation
CF-2016-07	2016-03-17	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Nose Landing Gear Assembly - Service Life Reduction
US-2016-05-01	2016-03-16	PIPER AIRCRAFT INC.	PA-31 (Navajo)	Fuselage - Bulkhead Assembly at Fuselage Station FS 317.75 - Repetitive Inspections / Repair /Modification
2015-0226R2	2016-03-15	AIRBUS HELICOPTER S, AIRBUS HELICOPTER S DEUTSCHLAN D, BELL HELICOPTER TEXTRON CANADA (BHTC), BELL HELICOPTER TEXTRON Inc. (BHTI), FINMECCANI CA S.p.A, MD HELICOPTER S INC (MDHI), SIKORSKY	SA 330 / AS 332 / EC 225, SA 365/366 / AS 365 / EC 155, EC135/635, MBB-BK 117, 429, 430, 212, 214, 412, A109/A119, AB139/AW139, AB212/AB412, MD900, S-61, S-76, S-92	Equipment / Furnishings - Hoist - Test / Replacement
CF-2014-19R1	2016-03-14	BOMBARDIER	CL-600 (Challenger)	Engine Exhaust - Engine Thrust Reverser Actuator Attachment Structure Failure
2016-0052	2016-03-14	EADS CASA	C-212	Flight Controls - Rudder Control System / Torque Tube Shaft - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0053	2016-03-14	AIRBUS	A319, A320, A321	Power Plant - Fan Cowl Door Latch with Key and Flag - Modification
2016-0054	2016-03-14	FINMECCANI CA S.p.A	AB212/AB412	Equipment / Furnishing - Comfort Clip Safety Belt - Removal
US-2016-04-16	2016-03-14	BOEING	DC-10, MD-10, MD-11	Fuel - Fuel System - Review