



Publ. number	Issue Date	TC Holder	Type	Subject
US-2016-08-06	2016-04-22	AIRBUS, SIMMONDS PRECISION PRODUCTS	A300-600, EASA STC 10016338, EASA.IM.A.S.02647, STC ST00092BO	Fuel - Outer Tank Overflow Sensor Harness - Inspection / Repair / Modification
2016-0079	2016-04-21	AIRBUS	A300, A300-600, A310	Doors - Forward Passenger Door Frame / Inner Flanges - Inspection / Repair
2016-0080	2016-04-21	AIRBUS	A300, A300-600, A300-600ST (Beluga), A310	Fuel - Fuel Pumps / Power Supply Circuit Breaker - Functional Test / Replacement / Fuel Pumps Replacement
2016-0078	2016-04-20	ROLLS-ROYCE PLC	RB211 TRENT 800	Engine - High Pressure Compressor Stage 1-4 Drum - Inspection
US-2016-07-28	2016-04-20	BOEING	DC-9, MD-88	Wings - Centre Wing Lower Skin - Inspection
2015-0209R1	2016-04-20	TURBOMECA	MAKILA 2	Engine - Centrifugal Diffuser Ferrule - Inspection
2016-0075	2016-04-19	EADS CASA	C-295, CN-235	Stabilizers - Elevator Hinge Fittings - Inspection
2016-0072	2016-04-19	CEAPR	DR 400	[Correction] Instruments & Control Panel - Electrical Wiring Harness - Modification
US-2016-07-03	2016-04-19	BOEING	747	Fuselage - Upper Chords of the Upper Deck Floor Beams - Inspection / Repair / Replacement
US-2016-07-16	2016-04-19	BOEING	737	Ice and Rain Protection - Coil Cord Assembly - Inspection / Replacement
2015-0241R1	2016-04-19	AIRBUS	A350	Flight Controls - Aileron Electro-Hydrostatic Actuator - Inspection / Replacement
2016-0077	2016-04-19	FINMECCANICA S.p.A	AB139/AW139	Landing Gear - Main Landing Gear Shock Absorber Screws - Replacement
2016-0076	2016-04-18	AIRBUS	A318, A319, A320, A321	Exhaust - Thrust Reverser Pivot Fitting - Inspection
US-2016-07-31	2016-04-15	BOEING	747	Fuselage - Sections 41 & 44 Upper Deck Floor Beam Upper Chords - Repetitive Inspections / Corrective Actions
2010-0262-CN	2016-04-15	ROLLS-ROYCE PLC	RB211 TRENT 900	CANCELLED: Engine Fuel & Control - Intermediate Pressure Turbine Overspeed Protection System Software - Introduction
2009-0051-CN	2016-04-15	ROLLS-ROYCE PLC	RB211 TRENT 900	CANCELLED: Engine - High Pressure Turbine Nozzle Guide Vane Convex Surface - Inspection
2016-0074	2016-04-15	AIRBUS	A350	Exhaust - Thrust Reverser Actuation System - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0073-E	2016-04-13	AIRBUS HELICOPTERS	SA 341/342	Landing Gear - Rear Cross-Tube - Inspection / Replacement
BR-2016-04-01	2016-04-13	EMBRAER	ERJ-190	Time Limits / Maintenance Checks - Airworthiness Limitation Section (ALS) / Maintenance Program - Revision
US-2016-07-24	2016-04-13	TEXTRON AVIATION INC.	310, 320 (Skyknight), 335, 340, 401, 402, 411, 414, 421	Flight Controls - Elevator Trim Push-pull Rod - Replacement / Inspection
BR-2016-04-02	2016-04-12	EMBRAER	EMB-500 (Phenom 100), EMB-505 (Phenom 300)	[Correction] Optimized Performance Analyzer (OPERA) Software Configuration / Airplane Flight Manual (AFM) Limitations Section - Inspection / Revision
US-2016-07-05	2016-04-12	BOEING	747	Oxygen - Passenger Oxygen System - Inspection / Installation
US-2016-07-21	2016-04-12	PIPER AIRCRAFT INC.	PA-28 (Archer), PA-28 (Warrior), PA-28R (Arrow)	Wings - Right Wing Rib - Inspection
2016-0070	2016-04-12	ATR	ATR42, ATR72	[Correction] Lights - Emergency Exit - Emergency Power Supply Unit - Inspection / Replacement
2016-0071	2016-04-11	EADS CASA	C-295, CN-235	Fuel - Motorised Fuel Valve - Inspection
2016-0068	2016-04-11	AIRBUS	A318, A319, A320, A321	SUPERSEDED BY EASA AD 2016-0076
2016-0069	2016-04-11	AIRBUS	A318, A319, A320, A321	Power Plant - Fan Cowl Door Latch with Key and Flag, CFM engines - Modification
2014-0179R2	2016-04-11	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Rotor Drive(s) - Tail Rotor Drive Flange - Inspection
US-2016-07-02	2016-04-11	HONEYWELL ENGINES	TFE731	Engine - Interstage Turbine Transition Ducts - Replacement