



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0202-E	2016-10-07	PILATUS AIRCRAFT LTD	PC-6	Fuselage - Rear Fuselage Stabilizer Trim Attachment Components - Inspection
2016-0199	2016-10-07	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter - Inspection ; Main Rotor Drive - Epicyclic Module - Replacement / Reduced Service Life Limit
CF-2016-32	2016-10-06	BOMBARDIER	CL-600 (Challenger)	Fuel - Engine and Auxiliary Power Unit Electrical Fuel Pump Cartridge/Canister Fuel Leakage
2016-0198	2016-10-06	AIRBUS	A300-600	Wings - Center Wing Box Frame 47 Angle Fittings - Inspection / Modification
CF-2016-30	2016-10-05	BOMBARDIER	CL-600 (Regional Jet)	Electrical Power - Inspection, Replacement and Modification of the Circuit Breakers Installation at the Cockpit Circuit Breaker Panels
2016-0197	2016-10-05	AIRBUS	A310	Fuselage - Upper Frame Bases-to-Arches Junctions from Frame 43 to Frame 46 - Modification
US-2016-20-06	2016-10-04	GULFSTREAM AEROSPACE CORPORATION	G-1159, GIV	Flight Controls - Elevator Assemblies and Skins - Maintenance / Inspection Program Revision [Life Limit]
US-2016-19-09	2016-10-04	GENERAL ELECTRIC	GE90	Engine - High-Pressure Compressor (HPC) Stage 8-10 Spool Seal Teeth - Inspection
2016-0193	2016-09-30	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - Low Pressure Turbine Exhaust Case and Support Assembly (Tail Bearing Housing) - Inspection / Replacement
2016-0195	2016-09-30	AIRBUS	A300-600, A310	Instruments - Electronic Centralized Aircraft Monitoring Symbol Generator Unit - Replacement
2016-0196	2016-09-30	AIRBUS	A310	Wings - Centre Wing Trellis Boom Drainage Holes & Frame 40 Upper Corner Fitting - Inspection / Repair
2016-0194	2016-09-30	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - Low Pressure Turbine Disc Seal Fins and Interstage Seals - Inspection / Replacement
CF-2016-31	2016-09-30	BOMBARDIER	DHC-8	Landing Gear - Dynamic Response of Main Landing Gear System to External Loads
US-2016-19-04	2016-09-28	BOEING	787	Equipment / Furnishings - Flight Crew Seat Assemblies - Test / Replacement
2016-0192	2016-09-28	SCHLEICHER, ALEXANDER	ASK 21	Aircraft Flight Manual - Amendment
CF-2016-28	2016-09-27	BOMBARDIER	BD-100	Electrical Power - Fouling Between the Auxiliary Power Unit (APU) Generator Power Cables and Hydraulic Return Line
CF-2016-11R1	2016-09-27	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Flight Controls - Corrosion of Bellcrank Pivot Bearings
2014-0205R2	2016-09-27	AIRBUS	A380	Wings - Movable Flap Track Fairing Number 4 Pivot Brackets - Inspection / Repair / Replacement / Modification



Publ. number	Issue Date	TC Holder	Type	Subject
2014-0049R2	2016-09-27	AIRBUS	A380	Wings - Movable Flap Track Fairing Number 3 and 4 Bracket Assemblies and Fasteners - Inspection / Replacement / Modification
2016-0191-E	2016-09-27	WSK PZL - SWIDNIK S.A.	SW4	Fuselage - Door Window Frame / Emergency Window Seal - Inspection
2016-0189	2016-09-26	AIRBUS	A380	Wings - Trailing Edge Flap Track #3 and #4 Support - Modification
2016-0190	2016-09-26	DIAMOND AIRCRAFT INDUSTRIES	DA 40, DA 42 / 62	Auto Flight - Auto-pilot Bridle Cable Clamps - Inspection / Replacement