



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0023	2017-02-10	AIRBUS	A300-600	Wing - Stringer Joint at Rib 18 - Inspection / Modification
US-2017-01-03	2017-02-09	BOEING	717	Standard Practices/Structures - Airworthiness Limitations Section - Amendment
2015-0038R1	2017-02-09	AIRBUS	A318, A319, A320, A321	Powerplant - Forward Engine Mount - Inspection
US-2017-02-06	2017-02-08	PIPER AIRCRAFT INC.	PA-31P, PA-31T (Cheyenne)	Electrical Power - Main Circuit Breaker Panel Wiring - Inspection
2017-0021	2017-02-08	AIRBUS	A330, A340	Fuselage - Cabin and Cargo Compartments Parts - Inspection / Replacement
2017-0022	2017-02-08	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection
US-2017-02-04	2017-02-08	BOEING	747	Nacelles / Pylons - Aluminum Strut Side Skin and Corrosion Resistant Steel Outer Spring Beam Support Fitting - Inspection
CF-2016-20R1	2017-02-08	BOMBARDIER	CL-600 (Regional Jet)	Equipment/Furnishings - Electrical Short of Bonding Jumper causing Burnt Water Supply Line and Smoke in Cabin
2011-0205R1	2017-02-07	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	[Correction] Stabilizers - Tail Fin Assembly - Inspection / Replacement
2017-0020-E	2017-02-07	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Tail Rotor - Pitch Rod - Inspection
2017-0018	2017-02-03	SOCATA	TBM 700	Flight Controls - Aileron Control - Modification
2017-0019-E	2017-02-03	SAFRAN HELICOPTER ENGINES	ARRIEL 1	Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement
2017-0017	2017-02-01	ROLLS-ROYCE PLC	TRENT 1000	Engine - Intermediate Pressure Compressor Rotor Seal - Inspection
2017-0015	2017-01-31	AIRBUS	A380	Fuselage - Belly Fairing - Inspection / Repair / Replacement
2017-0016	2017-01-31	328 SUPPORT SERVICES	Dornier 328	Fuel - Fuel Line Clamps - Inspection / Replacement
CF-2017-05	2017-01-30	BOMBARDIER	DHC-8	Fuel System - Motive Flow Line Fouling and Motive Flow Line and Pressure Relief Line Broken P-Clamps
2017-0014	2017-01-30	ROLLS-ROYCE DEUTSCHLAND	SPEY 506, SPEY 555	Engine - High Pressure Compressor Stage 12 Rotor Discs - Replacement [Life Limit]
2015-0141R3	2017-01-30	AIRBUS	A380	Wings - Leading Edge Shear Cleats - Inspection / Replacement