



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0066-E	2017-04-21	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
2017-0048	2017-04-20	AIRBUS	A300-600, A310	[Correction] Fuselage - Aft Cargo Door Sill Beam Area - Inspection / Modification
2017-0065	2017-04-19	CFM INTERNATIONAL	CFM56-5, CFM56-5B	Engine Fuel and Control - Hydro-Mechanical Units - Operational Limitations
US-2017-07-04	2017-04-18	GENERAL ELECTRIC	GE90	Engine - High Pressure Compressor (HPC) Rotor Stage 2-5 Spools - Removal
US-2017-08-06	2017-04-18	GENERAL ELECTRIC	GE90	Engine Oil - Fuel / Oil Lube / Servo Coolers ("Main Fuel Oil Heat Exchangers") - Replacement
US-2017-08-05	2017-04-18	GENERAL ELECTRIC	GE90	Engine - High-Pressure Compressor (HPC) Stage 8-10 Spool - Inspection
2013-0170R1	2017-04-18	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine Fuel & Control - Hydro-Mechanical Metering Unit - Inspection / Replacement
2017-0064-E	2017-04-12	SAFRAN HELICOPTER ENGINES	ARRIEL 1	Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement
US-2017-07-10	2017-04-12	AMERICAN CHAMPION AIRCRAFT CORP	8 series	Placards - Aerobatic Flight Prohibited - Installation // Wings - Aileron Hinge Rib and Support - Inspection
2017-0063	2017-04-12	AIRBUS	A330, A340	Fuselage - Frame 40 Skin Panel Junction - Inspection
CF-2015-16R2	2017-04-11	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Tail Rotor - Pitch Link Spherical Bearing Accelerated Wear
US-2017-06-09	2017-04-11	BOEING	787	Equipment / Furnishings - Closets / Video Stations - Fire Blok Installation Fuselage - Main Passenger Cabin Floor Panel Openings - Fire Blocking Tape Installation
2017-0062	2017-04-11	AIRBUS HELICOPTERS	AS 350 / EC 130	Rotors Flight Control - Collective Pitch Control - Inspection