



Publ. number	Issue Date	TC Holder	Type	Subject
US-2017-09-09	2017-06-16	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	ZODIAC SEATS CALIFORNIA LLC - Seating Systems - Removal
CF-2017-19	2017-06-14	BOMBARDIER	CL-600 (Regional Jet)	Flight Control - Rudder Travel Limiter - Return Springs Failure and Limiter Arm Lug Deformation
2017-0105	2017-06-14	AIRBUS	A330	Electrical Power - Alternating Current Emergency Generation - Flight Warning Computer Software Update
2017-0103	2017-06-14	AUSTRO ENGINE GMBH	E4	Engine - Timing Chain - Replacement / Aircraft Flight Manual - Limitations Section - Amendment
2017-0104	2017-06-13	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Time Limits / Maintenance Checks - Main Gearbox Magnetic Plugs - Inspection; Main Rotor Drive - Planet Gear Assemblies - Replacement
US-2017-11-10	2017-06-13	LYCOMING ENGINES	TIO-540	Engine Exhaust - Weld Joints / Exhaust Pipe Flange Mounting Nuts - Inspection / Check
2017-0102	2017-06-13	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine Fuel & Control - High Pressure / Low Pressure Fuel Pump Metering Unit - Inspection / Replacement
US-2017-11-15	2017-06-12	GENERAL ELECTRIC	CF6-80C	Engine - High-Pressure Turbine Spacer / Impeller - Replacement
US-2017-12-02	2017-06-12	GENERAL ELECTRIC	GENx	Engine Fuel & Control - Signal Fuel Manifold - Replacement
US-2017-11-04	2017-06-12	BOEING	767	[Corrected] Fuselage - Fuselage Skin at the Skin Lap Splices - Repetitive Inspections
US-2017-10-07	2017-06-09	BOEING	737	Fuselage - Aft Fuselage Skin - Inspection / Repair / Replacement
US-2017-10-08	2017-06-09	BOEING	737	Fuselage - Aft Fuselage Skin - Inspection / Repair / Replacement
US-2017-09-10	2017-06-09	BOEING	747	Wings - Front Spar Web - Inspection
2017-0101-E	2017-06-09	BRP-ROTAX GmbH & Co KG	912 S	Ignition - Ignition House Sealing Plug - Inspection
2017-0100	2017-06-08	GE AVIATION CZECH	M601	Engine - Power Turbine Disc - Replacement
CF-2017-20	2017-06-08	VIKING AIR LTD	DHC-6 (Twin Otter)	Flight Controls - Aileron Cable Wear At Wing Root Rib and At Fuselage Skin
2017-0099	2017-06-08	AIRBUS	A318, A319, A320, A321	Wings - Front Spar Vertical Stringers - Inspection
2017-0098	2017-06-07	AIRBUS	A319, A320, A321	Fuselage - Potable Water and Waste Water Service Panels - Reinforcement
2017-0097	2017-06-07	LEONARDO S.p.A. HELICOPTERS	AB212/AB412	Landing Gear - High Skid Landing Gear Aft Crosstubes - Life Limit
US-2017-10-16	2017-06-06	BOEING	787	Wings - Seam on the Outside and Inside of the Engine Struts - Inspection
US-2017-09-08	2017-06-06	BOEING	787	Electrical Power - Terminal Lugs - Inspection