



Publ. number	Issue Date	TC Holder	Type	Subject
2017-0255	2017-12-22	LEONARDO S.p.A. HELICOPTERS	AW169	Landing Gear - Main Landing Gear Weight on Wheels Support Bracket - Modification
DCA-750XL-24	2017-12-22	PACIFIC AEROSPACE LTD	750XL	Pitot Static Tube Support Clamps - Inspection
US-2017-24-05	2017-12-22	BOEING	737	[Correction] Wings - Upper Aft Skin - Inspection
2017-0242	2017-12-22	CZECH SPORT AIRCRAFT	PS-28 Cruiser	[Correction] Reciprocating Engine - Valve Push Rod Assembly - Inspection / Replacement
2017-0208	2017-12-22	BRP-ROTAX GmbH & Co KG	912 A, 912 F, 912 S, 914 F	[Correction] Reciprocating Engine - Valve Push Rod Assembly - Inspection / Replacement
2017-0256	2017-12-22	LEONARDO S.p.A. HELICOPTERS	AW189	SUPERSEDED BY EASA AD 2018-0006
CF-2017-38	2017-12-22	BOMBARDIER	CL-600 (Regional Jet)	Landing Gear - Main Landing Gear - Piston Axle Corrosion
DCA-750XL-23	2017-12-21	PACIFIC AEROSPACE LTD	750XL	Cockpit Control Handles - Inspection
DCA-750XL-22	2017-12-21	PACIFIC AEROSPACE LTD	750XL	Ventilation Hose behind Instrument Panel - Inspection
2017-0254	2017-12-21	DIAMOND AIRCRAFT INDUSTRIES	DA 42	Engine Exhaust - Exhaust Pipes - Modification / Inspection
DCA-750XL-21	2017-12-21	PACIFIC AEROSPACE LTD	750XL	Wing Lightning Protection Panels - Inspection
CF-2017-37	2017-12-21	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS CANADA LTD	AS 350 / EC 130, AS 355, EASA STC 10038250, LBA EMZ RC1024, STC SH94-29, STC SH96-62	Flight Controls - Restriction of directional control pedal movement
US-2017-26-03	2017-12-21	ENSTROM HELICOPTER CORPORATION	280, 480, F-28, TH-28	Main Rotor - Rod End Bearing Assemblies - Inspection
2017-0253-E	2017-12-21	ROLLS-ROYCE PLC	TRENT 1000	Engine - Removal / De-Pairing
2017-0250	2017-12-18	AUSTRO ENGINE GMBH	E4	Engine - Turbocharger Waste Gate Controller and Control Rod Circlip - Life Limit
CF-2017-36	2017-12-18	BELL HELICOPTER TEXTRON CANADA (BHTC)	505 (Jet Ranger X)	Indicating / Recording System - Engine Chip Detector Short to Ground