



Publ. number	Issue Date	TC Holder	Type	Subject
DCA-750XL-25A	2018-03-23	PACIFIC AEROSPACE LTD	750XL	Wing Leading Edge Tank Abrasion - Inspection
2011-0168R1	2018-03-23	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635, MBB-BK 117	Lights - Instrument Lighting Display Brightness - Modification
2018-0065	2018-03-23	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gearbox / Particle Detectors - Inspection
US-2018-04-08	2018-03-23	BOEING	737	Fuselage - Gore Webs, Gore Web Lap Splices and Repair Webs of the Aft Pressure Bulkhead - Repetitive Inspections
US-2018-06-05	2018-03-23	BOEING	737	Wings - Lower Wing Skin - Inspection
US-2018-04-06	2018-03-23	BOEING	737	Fuselage - Forward Entry Door Cut-out Intercostals / Frame Inner Chord - Inspection / Repair
2018-0066	2018-03-23	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gearbox / Particle Detectors - Inspection Main Rotor Drive - Planet Gear Assemblies - Replacement
2018-0041R1	2018-03-23	AIRBUS	A320, A321	Engine - Operational Restrictions
2018-0064	2018-03-23	AIRBUS	A330, A340	Hydraulic Power - Hydraulic Reservoir Pressure Relief Valve - Inspection / Replacement
2018-0067	2018-03-23	ENSTROM HELICOPTER CORPORATION	280, 480, F-28	Main Rotor - Hydraulic Damper / Belt Tension Shaft Rod End Assembly - Inspection
DCA-750XL-24A	2018-03-23	PACIFIC AEROSPACE LTD	750XL	Pitot Static Tube Support Clamps - Inspection
DCA-750XL-28	2018-03-23	PACIFIC AEROSPACE LTD	750XL	Elevator Bellcrank Pivot - Inspection
2018-0063	2018-03-22	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Rotors Flight Control - Cyclic Stick - Modification
2018-0060	2018-03-20	AIRBUS	A318, A319, A320, A321	Oxygen - Crew Oxygen / Oxygen Pipe Corrosion - Inspection
2018-0062	2018-03-20	AIRBUS	A330, A340	Hydraulic Power - Ram Air Turbine Hydraulic Pumps - Replacement
2018-0061	2018-03-20	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Main Rotor - Blades Thimble - Inspection
2018-0035-E	2018-03-16	WSK PZL - SWIDNIK S.A.	PZL W-3A	[Correction] Landing Gear - Bellcrank Assembly - Inspection
2017-0105R2	2018-03-16	AIRBUS	A330	Electrical Power - Alternating Current Emergency Generation - Flight Warning Computer Software Update
US-2018-06-08	2018-03-16	BOEING	757	Fuselage - Side Panel-to-Frame Attachments and Frames - Inspection
CF-2018-09	2018-03-15	BOMBARDIER	DHC-8	Furnishings - Forward Lavatory Door Hinge Flexing
CF-1997-18R1	2018-03-14	AIRBUS HELICOPTERS DEUTSCHLAND	BO 105	CANCELLED: Main Rotor System - Cracking of Rotor Mast
2018-0057	2018-03-14	AIRCRAFT INDUSTRIES	L 410/420 (Turbolet)	Propellers - Pitch Lock System - Modification / Check Aircraft Flight Manual - Amendment
2018-0058	2018-03-14	AIRBUS	A350	Flight Controls - Periodic Station Position Pick-Off Unit - Calibration Procedure
2018-0056	2018-03-14	AIRBUS HELICOPTERS DEUTSCHLAND	BO 105	Main Rotor Drive - Main Rotor Mast - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2015-0135R3	2018-03-13	AIRBUS	A318, A319, A320, A321	Navigation - Angle of Attack Sensors - Replacement
US-2018-04-07	2018-03-12	BOEING	747	Wings - Structural Significant Items (SSIs) - Revision of the Maintenance or Inspection Program / Inspection
US-2018-03-04	2018-03-12	APPLIANCES	ATA 34 NAVIGATION	ROSEMOUNT AEROSPACE INC. - Pitot Probes - Inspection / Replacement
2018-0055	2018-03-12	ROLLS-ROYCE DEUTSCHLAND	Tay	Time Limits / Maintenance Checks - Time Limit Manual - Amendment