



Publ. number	Issue Date	TC Holder	Type	Subject
US-2018-18-07	2018-09-07	BOEING	757	Fuselage - Skin Longitudinal Lap Splices - Inspection
2018-0201	2018-09-07	AIRBUS	A340	Fuel - Fuel Control and Monitoring Computer - Software Update
2018-0199	2018-09-06	ROLLS-ROYCE PLC	RB211 TRENT 900	Engine - Oil Service Pipe Sealing Rings - Replacement
2018-0198	2018-09-06	AIRBUS	A330	Nacelles / Pylons - Lower Aft Pylon Fairing Drain Pipe and U-Shapes - Inspection / Modification
2018-0200	2018-09-06	AIRBUS	A320	Electrical Power - Wing Electrical Installation - Modification
2016-0247-CN	2018-09-06	ROLLS-ROYCE PLC	TRENT XWB	CANCELLED: Engine Fuel & Control - P30 Sense Line Air Tube - Drainage / Inspection
2018-0196	2018-09-05	AIRBUS	A330	Flight Controls - Flight Control Primary Computer - Modification / Replacement
2018-0197	2018-09-05	LEONARDO S.p.A. HELICOPTERS	AW169, AW189	Windows - Emergency Exit Windows - Modification
2018-0188R1	2018-09-05	ROLLS-ROYCE PLC	RB211 TRENT 700	Engine - Low Pressure Compressor Blades - Inspection / Replacement
2018-0194	2018-09-04	ROLLS-ROYCE DEUTSCHLAND	BR700-715	Engine - High Pressure Turbine Stage 1 Turbine Blades and Blade Damper - Replacement
2018-0195	2018-09-04	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	ANJOU AERONAUTIQUE - Restraint Systems Rotary Buckle Sub Assembly - Removal from Service
2015-0141R5	2018-09-04	AIRBUS	A380	[Correction] Wings - Leading Edge Shear Cleats - Inspection / Replacement
2014-0016R6	2018-09-04	AIRBUS	A380	Wings - Wing Inboard Leading Edge Droop Nose Gooseneck - Inspection / Repair / Replacement
US-2018-16-14	2018-09-04	BELL HELICOPTER TEXTRON Inc. (BHTI)	212, 412	Emergency Flotation Section - Emergency Flotation System Tube Assembly - Replacement
2018-0193	2018-09-03	DASSAULT AVIATION	Fan Jet Falcon	Time Limits / Maintenance Checks - Supplementary Structural Inspection Program - Amendment
2018-0192	2018-09-03	AIRBUS	A340	Aircraft Flight Manual / Engine Bleed Air System - Amendment; Indicating & Recording System - Flight Warning Computer - Modification / Replacement
2018-0191	2018-09-03	AIRBUS	A380	Fuel - Fuel Pumps / Outboard Collector Cell Jet Pump - Inspection
2018-0190	2018-08-31	AIRBUS HELICOPTERS	EC175	Landing Gear - Nose Landing Gear A-Frame / Liner - Inspection
2018-0189	2018-08-30	AIRBUS	A318, A319, A320, A321	Navigation - Back Up Speed Scale / Aircraft Flight Manual - Amendment



Publ. number	Issue Date	TC Holder	Type	Subject
US-2018-15-04	2018-08-30	GENERAL ELECTRIC	CF6-80A, CF6-80C	Engine - High-Pressure Turbine Stage 1 and Stage 2 Disks - Inspection
2018-0186	2018-08-29	AIRBUS HELICOPTERS	EC 120 B	Main Rotor - Hub Scissors Attachment Bolts - Inspection / Replacement
2018-0185	2018-08-29	ROLLS-ROYCE PLC	RB211 TRENT 900	Powerplant - Drains Mast - Inspection / Replacement
2018-0187	2018-08-29	SAAB AB	2000	Fuel - Fuel Quantity Reading Probes and Low Level Sensors - Functional Check
2018-0115-CN	2018-08-29	ROLLS-ROYCE DEUTSCHLAND	BR700-710	CANCELLED: Engine - Accessory Gearbox Mount Assembly Tie Bolts - Replacement
2018-0184	2018-08-28	ATR	ATR72	Time Limits / Maintenance Checks - Certification Maintenance Requirements and Airworthiness Limitations - Amendments
2018-0182	2018-08-28	AIRBUS HELICOPTERS	AS 350 / EC 130	Tail Rotor - Blade - Life Limit / Re-identification
2018-0183	2018-08-28	AIRBUS HELICOPTERS	EC 120 B	Tail Rotor - Blade - Life Limit / Re-identification
CF-2018-23	2018-08-27	BELL HELICOPTER TEXTRON CANADA (BHTC)	206	Engine Turbine/Turboshaft - RPM (N2) Steady-State Operation Avoidance Range Limit
US-2018-17-01	2018-08-27	BELL HELICOPTER TEXTRON Inc. (BHTI)	212, 412	Engine Oil / Aircraft Fuel System - Oil / Fuel Check Valves - Replacement
2018-0180	2018-08-27	AIRBUS	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment
2018-0181	2018-08-27	BALONY KUBICEK	BB Hot Air Balloons	Fuselage - Envelope Vertical Load Tapes - Inspection