



Publ. number	Issue Date	TC Holder	Type	Subject
2018-0276R1	2019-01-11	AIRBUS	A330	Fuselage - Structural Parts / Joints - Modification / Reinforcement
US-2018-26-05	2019-01-11	BOEING	777	Fuel - Motor-Operated Valve Actuators / Maintenance or Inspection Program - Inspection / Replacement / Revision
US-2018-26-06	2019-01-11	BOEING	737	Doors - Main Landing Gear Center Door Assemblies - Inspection
US-2018-26-03	2019-01-11	BOEING	757	Equipment / Furnishings - IPECO 3A090 and 3A258 Flight Crew Seats - Inspection
US-2018-22-07	2019-01-11	ENGINE ALLIANCE LLC	GP7200	Engine - High Pressure Compressor Stages 2-5 Spool - Inspection / Replacement
2019-0002	2019-01-11	AIRBUS	A380	Nacelles / Pylons - Inboard and Outboard Pylon Drain System - Inspection
US-2018-23-12	2019-01-11	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	[Correction] ZODIAC AERO EVACUATION SYSTEMS - Fusible Plugs - Replacement
2019-0004	2019-01-11	APPLIANCES	ATA 34 NAVIGATION	THALES AVS FRANCE SAS - Global Navigation Satellite System - Operational Limitations
2019-0003	2019-01-11	AIRBUS HELICOPTERS	EC175	Rotor Drive - Main Gearbox Top Sensor - Inspection
CF-2019-02	2019-01-10	VIKING AIR LTD	DHC-6 (Twin Otter)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
CF-2019-01	2019-01-10	AIRBUS HELICOPTERS, BELL HELICOPTER TEXTRON CANADA (BHTC), BELLIS INVESTMENTS LTD, MD HELICOPTERS INC (MDHI)	AS 350 / EC 130, AS 355, 206, 407, STC SH98-35, 369, 500N	Standard Practices - Helicopter External Transport System (HETS _æ) - Unapproved Parts, Inadequate Service Life Limits and Maintenance Requirements
CF-2018-36	2019-01-10	BOMBARDIER	CL-600 (Challenger)	Navigation - Flight Instruments - Unreliable Air Data in the Cockpit
2019-0001	2019-01-10	AIRBUS HELICOPTERS	AS 350 / EC 130	Doors - Sliding Door Opening Mechanism - Inspection
2018-0265R1	2019-01-10	BRP-ROTAX GmbH & Co KG	914 F, 915	[Correction] Engine - Exhaust Valve - Replacement
2018-0137R1	2019-01-09	AIRBUS	A318, A319, A320, A321	Nacelles / Pylons - Pylon Aft Fixed Fairings - Inspection
CF-2018-37	2019-01-08	BOMBARDIER	BD-100	Recording System - Cockpit Voice Recorder (CVR) and Flight Data Recorder (FDR) power supply modification



Publ. number	Issue Date	TC Holder	Type	Subject
US-2018-25-17	2019-01-07	AIR COMM CORPORATION, AIRBUS HELICOPTERS, BELL HELICOPTER TEXTRON CANADA (BHTC)	CAA UK AAN 25273, EASA STC 10029555, STC EASA.IM.R.S.01173, STC EASA.IM.R.S.01537, STC SH2750NM, STC SR00222DE, STC SR00543DE, STC SR00643DE, AS 350 / EC 130, 206, 407	Air Conditioning - Electrical Connectors - Replacement