



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2019-10	2019-03-08	BOMBARDIER, ROCKWELL COLLINS	CL-600 (Challenger), EASA STC 10041712 , STC ST01505WI-D	Avionic System - Airplane Flight Manual Navigation System Limitations - Prohibit Editing CLIMB TO Altitudes and Use of Temperature Compensation on Flight Management System
CF-2019-09	2019-03-08	BOMBARDIER, ROCKWELL COLLINS	BD-100, STC ST01611WI-D	Avionic System - Airplane Flight Manual Navigation System Limitations - Prohibit Editing CLIMB TO Altitudes and Use of Temperature Compensation on Flight Management System
CF-2019-07	2019-03-08	VIKING AIR LTD	CL-215	Wing - Cracking of the Wing Lower Skin at Wing Station 51 under the Drag Angle
2019-0044	2019-03-07	AIRBUS	A300-600	Wings - Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction - Inspection / Repair
2019-0045-E	2019-03-07	WSK PZL - SWIDNIK S.A.	SW4	Tail Rotor - Rotor Blade Bearing(s) - Inspection
2019-0043	2019-03-06	TECNAM, Costruzioni Aeronautiche	P2006T	Landing Gear - Nose Landing Gear Piston Tube - Replacement
CF-2019-08	2019-03-06	BELL HELICOPTER TEXTRON CANADA (BHTC)	505 (Jet Ranger X)	Engine Fuel and Control - Change of Flight Manual Limitation for Jet B and JP-4 Fuels
CF-2019-06	2019-03-01	BOMBARDIER	DHC-8	Fuselage - Non-Conforming Keel Tension Fittings and Stringer End Fittings
BR-2019-02-02	2019-02-28	EMBRAER	ERJ-170, ERJ-190	Fuselage - Ram Air Turbine Compartment Door Seal Attachment - Inspection / Rework
2019-0042	2019-02-27	AIRBUS	A330	Power Plant - Engine Air Inlet Cowl Acoustic Panels - Inspection / Repair / Replacement
2017-0103R1	2019-02-25	AUSTRO ENGINE GMBH	E4	Engine - Timing Chain - Replacement / Aircraft Flight Manual - Limitations Section - Amendment
US-2019-02-01	2019-02-25	GENERAL ELECTRIC	GEnx	Engine - High-Pressure Turbine Stator Cases - Removal / Replacement
2019-0041	2019-02-25	AUSTRO ENGINE GMBH	E4	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment