



Publ. number	Issue Date	TC Holder	Type	Subject
US-2019-11-08	2019-06-14	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	Engine - Main Gearbox Assembly and Electronic Engine Control Software - Removal / Installation
US-2019-11-06	2019-06-14	BOEING	737	Fuselage - Skin under the Drag Link Assembly - Inspection
2019-0143	2019-06-13	GE AVIATION CZECH	M601	Engine - Power Turbine Disc - Inspection / Replacement
2019-0137	2019-06-12	CFM INTERNATIONAL	LEAP-1B	Engine - Transfer Gearbox Module Scavenge Screens - Inspection
2019-0139	2019-06-12	AIRBUS HELICOPTERS	EC 120 B	Main Rotor - Hub Scissors / Attachment Bolts - Inspection / Replacement
2019-0140	2019-06-12	AIRBUS	A330	Oxygen - Chemical Oxygen Generators - Replacement
2019-0138	2019-06-12	AIRBUS	A330, A340	Stabilizers - Elevators - Inspection
CF-2011-42R1	2019-06-12	BELL HELICOPTER TEXTRON CANADA (BHTC)	407	Fuselage - Longerons Cracking - Inspection / Repair.
2019-0135	2019-06-11	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - Intermediate Pressure Turbine Blades - Replacement
2019-0136	2019-06-11	LEONARDO S.p.A. HELICOPTERS	AW189	Rotorcraft Flight Manual - Emergency Procedures Section - Amendment
CF-2019-22	2019-06-11	BOMBARDIER	CL-600 (Regional Jet)	Electrical Power - Electrical Wires Chafing With Auxiliary Aft Cabin Fuel Tank Bracket
US-2019-11-03	2019-06-11	BOEING	737	Flight Controls - Main Slat Track Assemblies - Identification / Replacement
2019-0131	2019-06-11	DASSAULT AVIATION	Falcon 2000	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2019-0133	2019-06-11	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2019-0134	2019-06-11	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2019-0132	2019-06-11	DASSAULT AVIATION	Mystère-Falcon 900	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment



Publ. number	Issue Date	TC Holder	Type	Subject
2015-0226R4	2019-06-11	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND , BELL HELICOPTER TEXTRON CANADA (BHTC), BELL HELICOPTER TEXTRON Inc. (BHTI), LEONARDO S.p.A. HELICOPTERS, MD HELICOPTERS INC (MDHI), SIKORSKY	SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117, 429, 430, 212, 214, 412, A109/A119, AB139/AW139, AB212/AB412, MD900, S-61, S- 76, S-92	Equipment / Furnishings - Hoist - Test / Replacement
2019-0130-E	2019-06-07	STEMME AG	S12	Main Landing Gear - Upper Connection - Inspection / Repair
2019-0129	2019-06-06	PILATUS AIRCRAFT LTD	PC-12	Stabilizers - Horizontal Stabilizer Rear Attachment Bolts - Inspection / Replacement
2019-0128	2019-06-06	PIPISTREL VERTICAL SOLUTIONS d.o.o.	Virus SW 121	Equipment / Furnishings - Seat Belt Attachment Points / Bolts - Inspection / Replacement
2019-0127	2019-06-05	AIRBUS	A380	Wings - Trailing Edge Flap Track #3 and #4 Supports - Modification
2019-0123	2019-06-05	AIRBUS	A380	Landing Gear - Gravity Extension System - Inspection / Modification
2019-0126	2019-06-05	AIRBUS	A350	Fuselage - Forward Cargo Door Upper Frame Fittings and Brackets - Inspection / Modification
2019-0125	2019-06-05	BUCHER LEICHTBAU AG, EMBRAER	EASA STC 10030758, STC EASA.A.S.0371 2, ERJ-170, ERJ-190	Equipment / Furnishing - 9G NGS XL StepX Stretcher 1120050-Series - Modification
2019-0124	2019-06-05	AIRBUS	A380	Electrical Power - Ram Air Turbine Free Rotation - Manual Check
US-2019-08-02	2019-06-04	BOEING	737	Fuselage - Fuselage Upper Frames, Side Frames, Fail-safe Chords, Inboard Chords, Frame Webs, Stringers - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2019-09-02	2019-06-04	BELL HELICOPTER TEXTRON Inc. (BHTI)	212, 412	Engine Oil / Aircraft Fuel System - Oil / Fuel Check Valves - Replacement
RU-2019-322-04	2019-06-04	SUKHOI CIVIL AIRCRAFT, JSC	RRJ-95	Airworthiness / Maintenance Records Check
US-2019-08-03	2019-06-04	BOEING	737	Fuselage - Section 43 Lower Lobe Frames - Inspection
2019-0122	2019-06-04	AIRBUS	A318, A319, A320, A321	Fuselage - Side Box Beam Flange in Frame 43 Area - Inspection / Repair / Modification
2018-0254R1	2019-06-04	328 SUPPORT SERVICES	Dornier 328	Wings - Roll Spoiler Bearing Arms - Inspection
CF-2019-20R1	2019-06-03	BOMBARDIER	CL-600 (Regional Jet)	Decompression Panel - Flight Compartment Door - Upper Panel