



Publ. number	Issue Date	TC Holder	Type	Subject
2019-0194-E	2019-08-09	LEONARDO S.p.A. HELICOPTERS	A109/A119	Tail Rotor - Tail Rotor Duplex Bearing and Plug - Inspection
2019-0086R1	2019-08-09	CRANFIELD AEROSPACE SOLUTIONS Ltd., TEXTRON AVIATION INC.	EASA STC 10056170 , 525 (CitationJet)	Flight Controls - Active Technology Load Alleviating System - Deactivation / Modification ; Airplane Flight Manual Supplement - Amendment
2019-0193	2019-08-07	LEONARDO S.p.A. HELICOPTERS	AW169, AW189	Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check
2019-0192	2019-08-05	AIRBUS	A380	Electrical Power - Ram Air Turbine Free Rotation - Manual Check
2018-0249R1	2019-08-02	AIRBUS	A330, A340	[Correction] Wings - Centre Wing Box Fastener Holes at Frame 40 Vertical Web - Inspection / Modification
2019-0187	2019-08-02	GUIMBAL, HELICOPTERES	CABRI	[Correction] Powerplant - Engine Cooling Fan - Replacement
CF-2002-39R2	2019-08-02	BOMBARDIER	CL-600 (Regional Jet)	Fuselage Pressure Floor Skin
CF-2014-08R1	2019-08-01	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Doors - Translating Doors Loose Bolts
CF-2010-30R2	2019-08-01	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Cracking of the Nacelle Attachment Fitting(s)
2019-0189	2019-07-31	AIRBUS	A320	Aircraft Flight Manual Section Limitations - Amendment
2019-0171R1	2019-07-31	AIRBUS	A321	Aircraft Flight Manual Section Limitations - Amendment
2019-0190	2019-07-31	AIRBUS	A300	Hydraulic Power - Hydraulic Reservoir Air Pressurization System Lines - Functional Tests
2019-0188	2019-07-31	AIRBUS	A300-600, A300-600ST (Beluga), A310	Hydraulic Power - Hydraulic Reservoir Air Pressurization System Lines - Functional Tests
2019-0191-E	2019-07-31	WSK PZL - SWIDNIK S.A.	PZL W-3A	Equipment / Furnishings - Hoist Carrier Assembly Bracket / Bolts - Inspection / Replacement
2019-0185	2019-07-30	GUIMBAL, HELICOPTERES	CABRI	Rotors Flight Control - Main Rotor / Swashplate Guide Bellcrank Bushing - Replacement
2019-0186	2019-07-30	GUIMBAL, HELICOPTERES	CABRI	Rotors Flight Control - Main Rotor / Non-Rotating Scissor Link - Replacement
DCA-750XL-38	2019-07-29	PACIFIC AEROSPACE LTD	750XL	Flap Assembly Screw Jack - Inspection
2019-0184	2019-07-29	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355, SA/AS 365 / EC 155	Rotors Flight Control - Main Rotor Servo Actuators - Inspection