



Publ. number	Issue Date	TC Holder	Type	Subject
2019-0209	2019-08-23	SAFRAN HELICOPTER ENGINES	MAKILA 1	Power Plant - Control and Monitoring Harness - Identification / Replacement
2019-0208	2019-08-22	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Integrated Modular Avionics - Aircraft Management Computer Software - Update
2019-0207	2019-08-22	AIRBUS	A350	Doors - Passenger / Crew Door Girt Bar Fitting Assemblies - Inspection
CF-2019-30	2019-08-21	PRATT & WHITNEY CANADA	PT6A-100, PT6A-30	Compressor Turbine (CT) Blade Fracture due to Non-conforming CT Vane Installation
2019-0201	2019-08-20	DASSAULT AVIATION	Mystère-Falcon 20	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
US-2019-15-06	2019-08-20	ENGINE ALLIANCE LLC	GP7200	Engine - High Pressure Compressor Stages 2-5 Spool - Inspection
US-2019-16-01	2019-08-20	INTERNATIONAL AERO ENGINES AG	V2500-()5	Engine - Turbine Exhaust Case - Inspection
US-2019-16-04	2019-08-20	ENGINE ALLIANCE LLC	GP7200	Engine - Fan Hub Assembly - Inspection / Replacement
US-2019-14-13	2019-08-20	BOEING	767	Equipment / Furnishings - Flight Crew Seats - Inspection / Check
2019-0205	2019-08-20	AIRBUS	A380	Pneumatic - Engine Bleed Air System Certification Maintenance Requirements Task - Amendment
2019-0203	2019-08-20	AIRBUS	A350	Electrical Power - Ram Air Turbine Performance - Modification (Software Update)
2008-0221-CN	2019-08-20	DASSAULT AVIATION	Falcon 10, Falcon 2000, Falcon 7X, Falcon 900EX, Fan Jet Falcon, Mystère-Falcon 20, Mystère-Falcon 20GF/200, Mystère-Falcon 50, Mystère-Falcon 900	CANCELLED: Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2019-0206	2019-08-20	AIRBUS	A350	Fuselage - Trimmable Horizontal Stabilizer Fittings and Bearing Assembly Attachment Interface - Inspection
2019-0200	2019-08-20	DASSAULT AVIATION	Mystère-Falcon 20	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2019-0202	2019-08-19	WSK PZL - SWIDNIK S.A.	PZL W-3A	Main Rotor - Blade Droop Stops - Removal from Service
2019-0199	2019-08-16	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Tail Rotor Drive - Ti-Bolt - Inspection / Replacement
2019-0198	2019-08-15	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Flight Controls - Wiring Harness - Modification
2019-0197	2019-08-14	AIRBUS	A318, A319, A320	Fuel - Fuel Level Sensor Support Bracket - Replacement
2019-0196	2019-08-14	AIRBUS	A318, A319, A320, A321	Fuselage - Cabin, Cargo Compartment and Airframe Parts - Inspection / Replacement [Improper Heat Treatment]
2019-0195	2019-08-13	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Tail Rotor - Hub Assembly - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2019-29	2019-08-13	BOMBARDIER	BD-100	Flight Controls - Multi-Function Spoiler Jam
US-2019-16-02	2019-08-12	GE HONDA AERO ENGINES, LLC	HF120	Engine Fuel Control - Fuel Pump Metering Unit - Replacement