



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2019-43	2019-11-15	BOMBARDIER	BD-100	Landing Gear - Nose Landing Gear Shock Strut Cylinder Corrosion
US-2019-21-08	2019-11-15	TEXTRON AVIATION INC.	33 (Bonanza), 35 (Bonanza), 36 (Bonanza)	Aileron Control System - Right Aileron Flight Control Cable End Fittings - Inspection / Replacement
2019-0279	2019-11-15	AIRBUS	A320	Fire Protection - Cargo Compartment Fire Extinguishing Pipes - Inspection / Modification
BR-2019-11-08	2019-11-14	EMBRAER	EMB-505 (Phenom 300)	Stabilizers - Control Surface Mass-balance Weights and Attachments - Inspection / Replacement
US-2019-22-10	2019-11-13	BOEING	737	Fuselage - Frame Fittings and Failsafe Strap Outboard Chords - Inspection
2019-0267R1	2019-11-13	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	[Correction] Tail Rotor - Double Bearing - Inspection / Replacement
2019-0278	2019-11-12	ATR	ATR42, ATR72	Electronic Common Installation - Engine Nacelle Electrical Wiring - Modification; Hydraulic Power - Underwing Box Hydraulic Pipe - Inspection / Replacement
2019-0181R1	2019-11-12	AIRBUS	A350	Fuselage - Forward and Aft Cargo Door Latch Fitting External Lugs - Inspection / Modification
2019-0277-E	2019-11-12	SAFRAN HELICOPTER ENGINES	RTM 322	Air - Anti-icing Valve Assembly Gaskets - Replacement
BR-2019-11-06	2019-11-11	EMBRAER	EMB-505 (Phenom 300)	SUPERSEDED BY ANAC BRAZIL EMERGENCY AD 2019-11-08
2019-0088R1	2019-11-08	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155	Placards and Markings - Inspection / Installation
2019-0275	2019-11-07	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Power Plant - Engine Mount Bushings - Inspection / Replacement
CF-2019-38	2019-11-07	BOMBARDIER	BD-700	Electrical Power - Ram Air Turbine Deployment Actuator Galling
CF-2019-39	2019-11-07	DIAMOND AIRCRAFT INDUSTRIES, INC.	DA 40	Fuel System - Fuel Tank Connection Hose Deterioration
CF-2019-40	2019-11-06	BOMBARDIER	CL-600 (Regional Jet)	Navigation System - Flight Management System, Inertial Reference System and Attitude and Heading Reference System - Outdated Magnetic Variation Tables
2019-0274	2019-11-06	DAHER AEROSPACE	TB	Landing Gear - Main Landing Gear Leg - Inspection
2019-0273	2019-11-04	DASSAULT AVIATION	Falcon 2000, Falcon 900EX	Airplane Flight Manual - Section Normal Procedures - Amendment



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2019-19R1	2019-11-04	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Fuel Feed Tube Damage at Bonding Clamp Location Inside the Fuel Tank