



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0048	2020-03-06	LEONARDO S.p.A. HELICOPTER S	AW169, AW189	Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check / Modification
US-2020-03-16	2020-03-04	TEXTRON AVIATION INC.	210 (Centurion)	Fuselage - Carry-Thru Spar Lower Cap - Inspection
2020-0047	2020-03-04	SUKHOI CIVIL AIRCRAFT, JSC	RRJ-95	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2020-0046	2020-03-04	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine Fuel & Control - Full Authority Digital Engine Control B / Digital Engine Control Unit - Inspection / Replacement
2019-0291R1	2020-03-04	AIRBUS	A330, A340	Fuel - Fuel Pump - Inspection
2020-0045	2020-03-04	PIPISTREL VERTICAL SOLUTIONS d.o.o.	Virus SW 121	Fuel - Fuel Pressure Sensor - Inspection / Replacement
2020-0010R2	2020-03-04	ROLLS- ROYCE DEUTSCHLAN D Ltd & Co KG	TRENT 1000	Engine - De-Pairing Limitation
2020-0044	2020-03-03	CFM INTERNATION AL	CFM56-5B, CFM56-5C, CFM56-7B	Engine - High-Pressure Turbine Inner Stationary Seal - Inspection
2020-0043	2020-03-02	AIRBUS HELICOPTER S	SA/AS 365 / EC 155	Main Rotor Drive - Main Gearbox - Replacement
2020-0041	2020-02-28	ROLLS- ROYCE DEUTSCHLAN D Ltd & Co KG	RB211 TRENT 900	Engine - Intermediate Pressure Compressor Rotor Shaft - Inspection
US-2020-03-22	2020-02-28	BOEING	787	Wings - Frame Tie Rod Assemblies & Stub Beam Upper Chords - Inspection
2020-0042	2020-02-28	AIRBUS HELICOPTER S	EC175	Main Rotor Drive - Main Gearbox Top Sensor / Main Rotor Mast Lubrication System - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-01-18	2020-02-28	BOEING	757	[Correction] Time Limits / Maintenance Checks - Airworthiness Limitations Instructions - Principal Structural Elements - Inspections / Maintenance or Inspection Program Revision
2020-0037	2020-02-28	AIRBUS	A318, A319, A320, A321	[Correction] Fuselage - Frame Foot Coupling at Frame 43 - Inspection / Repair
2020-0040	2020-02-28	AIRBUS	A319, A320	Fuselage - Overwing Emergency Exit Cut-Outs in Section 15 - Modification
2015-0036R2	2020-02-27	AIRBUS	A318, A319, A320, A321	Fuselage - Fuselage Skin Repairs - Inspection
2020-0039	2020-02-27	BELL HELICOPTER TEXTRON Inc. (BHTI), BELL TEXTRON CANADA LTD (BTCL), CALIFORNIA HELICOPTER AIRWAYS INC., ERICKSON AIR-CRANE, KAMOV, SIKORSKY	204B, 205, 212, 214, 214ST, 412, 222, 230, 430, S-58, S-64, KA32, S-61, S-76, S-92	Fire Protection - Hand-held Fire Extinguishers - Replacement
CF-2020-02	2020-02-27	BOMBARDIER	CL-600 (Challenger)	Auto Flight System - Airplane Flight Manual Limitations and Procedures - Velocity Decay during Low Level Altitudes Capture in One Engine Inoperative Conditions
2020-0038	2020-02-27	WSK PZL - SWIDNIK S.A.	PZL W-3A	Main Rotor - Vibration Absorber Fairing - Installation
2020-0035	2020-02-26	ROLLS- ROYCE DEUTSCHLAN D Ltd & Co KG	TRENT XWB	Engine Fuel & Control - Engine Electronic Controller Software - Update
2020-0036	2020-02-26	AIRBUS	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Implementation
US-2020-03-10	2020-02-25	BOEING	737	Fuselage - Fairing Panel 194E, Wheel Well Panel 193D & Support Structure - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-04-01	2020-02-25	PRATT & WHITNEY	PW1500G, PW1900G	Engine - LP10 Oil Supply Tube & Fuel Oil Cooler - Inspection
2020-0033	2020-02-25	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Hydro-mechanical Metering Unit / Drive Link Splines - Inspection
2020-0034	2020-02-25	AIRBUS	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements - Implementation