



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0123	2020-05-29	AIRBUS	A350	Wings - Centre Wing Box Fasteners - Replacement
2020-0122	2020-05-29	AIRBUS	A320, A321	Equipment / Furnishings - Overhead Stowage Compartment Fixation Brackets - Inspection
2020-0124	2020-05-29	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine Fuel and Control - Fuel Pump - Replacement [Life Limitation]
2020-0097R1	2020-05-28	ATR	ATR42, ATR72	Fuselage - Passenger Seat Tracks - Inspection / Repair / Replacement
2020-0121	2020-05-28	B/E AEROSPACE FISCHER GmbH, FIBERGLAS TECHNIK R. LINDNER	ASTIR CS TOP, Grob Sailplanes	Flight Controls - Elevator Control Pushrod - Inspection / Replacement
2020-0110R1	2020-05-27	AIRBUS	A300	Fuselage - Structure, Windshield Frame and Closing Panel / Skin Lap Joint / Centre Wing Bottom Skin - Inspection
2020-0111R1	2020-05-27	AIRBUS	A300-600	Fuselage / Wings - Structure, Windshield Frame and Closing Panel / Outer Wing Bottom Skin - Inspection
2020-0112R1	2020-05-27	AIRBUS	A310	Fuselage - Structure, Windshield Frame and Closing Panel / Circumferential Junction Areas - Inspections
2020-0120	2020-05-27	PILATUS AIRCRAFT LTD	PC-6	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
CF-2020-19	2020-05-27	AIRBUS CANADA LP	BD-500 (A220 Series)	Oxygen - Crew - Inspection and Removal of a Protective End Cap Obstructing an Extraction Duct
2020-0119	2020-05-26	AIRBUS HELICOPTERS	EC175	Equipment / Furnishings - Emergency Locator Transmitter - Inhibition / Replacement
US-2020-10-10	2020-05-26	BOEING	DC-9, MD-88	Wings - Centre Wing Lower Skin - Inspection
BR-2020-05-02	2020-05-26	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 190	Flight Controls - Horizontal Stabilizer Control Yoke Assemblies - Modification
BR-2020-05-01	2020-05-26	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 170	Flight Controls - Horizontal Stabilizer Control Yoke Assemblies - Modification
US-2020-10-05	2020-05-25	APPLIANCES	ATA 34 NAVIGATION	ROCKWELL COLLINS INC. - Flight Management Computing Hardware System / Airplane Flight Manual - Revision
US-2020-06-19	2020-05-25	BOEING	727	Navigation - Angle of Attack Sensors - Inspection
CF-2020-18	2020-05-25	BELL TEXTRON CANADA LTD (BTCL)	429	Indicating / Recording System - Rotorcraft Flight Manual - Prohibit the use of Map-Mode on Left Hand Side and Right Hand Side Display Units
CF-2020-17	2020-05-22	AIRBUS CANADA LP	BD-500 (A220 Series)	Oxygen - Crew - Leak Check of the Lavatory A Oxygen Supply Line for the Third Crew Member



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0118	2020-05-22	AIRBUS	A319, A320, A321	Aircraft Flight Manual / Section Limitations - Amendment
BR-2020-04-01R1	2020-05-22	EMBRAER	EMB-545/-550 (Legacy 500)	Windows - Cockpit Side Windows - Inspection / Replacement
2020-0116	2020-05-20	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2020-0115	2020-05-20	DASSAULT AVIATION	Mystère-Falcon 900	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2020-0114	2020-05-20	DASSAULT AVIATION	Falcon 2000	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2020-0113	2020-05-20	DASSAULT AVIATION	Falcon 2000	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
2020-0117	2020-05-20	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 - Amendment
CF-2020-16	2020-05-19	BOMBARDIER	BD-700	Cabin Pressure Control System - Safety Valve - Overtorque