



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-11-07	2020-06-12	MD HELICOPTERS INC (MDHI)	369, 500N, 600N	Main Rotor System - Hub Lead-lag Bolts - Removal
2020-0133	2020-06-10	AIRBUS	A318, A319, A320, A321	Fire Protection - Cargo Door Seals - Cleaning / Greasing
2020-0132	2020-06-08	AIRBUS HELICOPTERS	EC175	Stabilizers - Horizontal Stabilizer Attachment Bolts - Inspection / Modification / Clearance Check; Rotorcraft Flight Manual - Amendment
2020-0130	2020-06-08	AIRBUS	A318, A319, A320, A321	Landing Gear - Main Landing Gear Torque Link Apex Pin - Replacement / Inspection
2020-0129	2020-06-05	AIRBUS	A380	Pneumatic - Overheat Detection System / Insulation Mufflers - Modification / Replacement
2020-0131	2020-06-05	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Equipment / Furnishings - Hoist Cable Cutter Frame - Modification
TCD-4753B-2020	2020-06-05	MITSUBISHI HEAVY INDUSTRIES LTD.	MU-2B (Japan production)	AFM Limitations Change - Pilot Training - Icing Conditions
2020-0127	2020-06-04	DASSAULT AVIATION	Falcon 10	Ice and Rain Protection - Wing Anti-Ice Outboard Flexible Hoses - Inspection
2020-0128	2020-06-04	LEONARDO S.p.A. HELICOPTERS	A109/A119	Tail Rotor - Tail Rotor Duplex Bearing and Plug - Inspection
2020-0126	2020-06-03	AIRBUS	A350	Flight Controls - Flap Drive Struts and Lever Bearing Assemblies - Inspection
CF-2020-21	2020-06-03	BELL TEXTRON CANADA LTD (BTCL)	429	Equipment / Furnishings - Incorrectly Manufactured Emergency Flotation System Supply Hoses
BR-2020-05-03	2020-06-02	EMBRAER	EMB-500 (Phenom 100), EMB-505 (Phenom 300)	Aircraft Flight Manual - Operational Envelope Temperature / Minimum Airspeed Limitation - Amendment
2020-0125	2020-06-02	AIRBUS	A320	Aircraft Flight Manual Section Limitations - Amendment
2019-0171R2	2020-06-02	AIRBUS	A321	Aircraft Flight Manual Section Limitations - Amendment